

APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	HM Tongeren
Make:	BMW
Model / version:	2 GRAN TOURER DIESEL - 2018
Vin:	WBA6W510205S49095
Plate:	
Mileage:	77100
First registration:	15/01/2021
Color:	

ADDITIONAL INFORMATION



Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES





VIN INFORMATION

Radio
7 rapports
Projecteurs à LED
Matière : alliage
Diamètre arrière 17
Diamètre avant 17
Hauteur arrière 55
Largeur avant 205
Climatisation réfrigérant 1234YF
1496 cm3
115 ch
Rétroviseur droit chauffant

Siège avant gauche chauffant
Volant cuir
Aide au stationnement avant
Caméra avant
Ouverture du coffre électriquement
Vitres portes arrière teintées foncées
Toit ouvrant électrique

Système navigation
2020
Equipeement Advantage
Lettre repère (J)
Largeur avant 7,5
Diamètre arrière 17
Indice de vitesse avant H
Largeur arrière 205
Accoudoir central avant
1.50 litre
Minérale vernissée
Rétroviseurs rabattables électriques

Sièges avant chauffants
Volant sport
Aide au stationnement arrière
Caméra arrière de recul
Appel de secours
Vitres de custode teintées foncées
Toit ouvrant vitré panoramique

Transmission automatique
Juillet
Entourage de vitres chromé
Diamètre avant 17
Largeur arrière 7,5
Hauteur avant 55
Indice de vitesse arrière H
Climatisation automatique 2 zones
Diesel
85 kw
Rétroviseur gauche chauffant
Rétroviseur intérieur jour/nu
automatique
Garnitures simili-cuir
Volant multifonction
Assistance au parking
Régulateur automatique de la distance
Lunette arrière teintée foncée
détecteur de pluie essuie-vitre
Attelage avec boule amovible

Fixotoit aluminium satiné	Protection piéton	Freinage d'urgence assistée autonome (urbain)
Avertisseur de collision avant	Contrôle pression des pneus	réservoir carburant de grande capacité
mesures CO2 étendues	Teleservices	tuner DAB
pack de rangement	boulons antivol de roue	encarts intérieurs argent Oxyx foncé mat
spécifique Europe		

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	×	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	×
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:		Fast charging cables:	

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	4 mm			Winter		?
Front right	4 mm			Winter		?
Rear left	4 mm			Winter		?
Rear right	4 mm			Winter		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Boot lid covering R	Scratch(es)
2	Alloy rim RR	Grooved
3	Door RR	Dent(s) and scratch(es)
4	Alloy rim FR	Scratch(es)
5	Bumper F	Scratch(es)
6	Alloy rim FL	Grooved

Total: 6

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
7	Bodywork	Scratch(es)	✓	×	×

Total: 1

DAMAGES DETAILS

1 - Boot lid covering R - Scratch(es)






2 - Alloy rim RR - Grooved



3 - Door RR - Dent(s) and scratch(es)



4 - Alloy rim FR - Scratch(es)






5 - Bumper F - Scratch(es)



6 - Alloy rim FL - Grooved



7 - Bodywork - Scratch(es) - Renta®



SIGNATURE