



CITROEN C5 AIRCROSS

Immatriculation	-
VIN	VR7A4DGZSNL014714
Kilométrage	97 416 km
Première immatriculation	14/06/2022
Couleur carrosserie	Gris

DÉTAILS DE L'INSPECTION

Adresse d'inspection	Date de l'inspection	20/04/2026 15:40:35
Adresse d'inspection		

INFORMATIONS SUR LE VÉHICULE

Marque	CITROEN	Type de carrosserie	Break
Modèle	C5 AIRCROSS	Nbre portes	5
VIN	VR7A4DGZSNL014714	Nbre sièges	5
Première immatriculation	14/06/2022	Transmission	Avant
Kilométrage	97 416 km	Couleur intérieur	Noir
Catégorie	Vehicule particulier	Couleur carrosserie	Gris

DOCUMENTS ET CLÉS

Nbre clés total	2	Certificat immatriculation (original)	Non
Nbre clés télécommandes	2	Certificat immatriculation (original)	N/A
Manuel d'utilisation	Oui		

OPTIONS

Batterie fonctionnante	Oui	Camera de recul	Oui
Moteur fonctionnant	Oui	Cache bagages	Oui
Véhicule roulant	Oui	Compresseur	Oui
Niveau carburant	25	Kit réparation	Oui
GPS	Oui	Nature de peinture	Metallisé

DAMAGES




Door RL

Damage type

Dent(s) and scratch(es)

Repair mode

Repair and paint (complete)



Door FL

Damage type

Dent(s) and scratch(es)

Repair mode

Repair and paint (complete)



Door FR

Damage type

Scratch(es)

Repair mode

Paint



Bumper R

Damage type	Scratch(es)
Repair mode	Paint



Tyre FL

Damage type	Out of tolerance
Repair mode	Replace



Tyre RR

Damage type	Out of tolerance
Repair mode	Replace



Tyre FR

Damage type	Out of tolerance
Repair mode	Replace



Centre console

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)





Interior

Damage type	Stain
Repair mode	Cleaning



Centre console

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)



Alloy rim FL

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)



Glove compartment lid

Damage type	Scratch(es)
Repair mode	Smart repair



Interior trim

Damage type	Broken
Repair mode	Replace



Tyres

Damage type	No damage
Repair mode	Acceptable



Alloy rim RL

Damage type	Scratch(es)
Repair mode	Acceptable





Alloy rim FR

Damage type	Scratch(es)
Repair mode	Acceptable



Wing trim RL

Damage type	Scratch(es)
Repair mode	Acceptable



Side repeater R

Damage type	Scratch(es)
Repair mode	Acceptable



Bumper moulding R

Damage type	Scratch(es)
Repair mode	Acceptable

COMMERCIAL PHOTOS

