Skoda

SKODA KAROQ (NU)(2017->) STYLE MOTEUR 1,5 LITRE(S) - 110 KW 16V TSI ACT 5 PORTES

VIN: TMBJR7NU1NC201457



Description

Registration number 2BTS776	**Registration date** 18/03/2022	**Odometer** 86894 km
Color Bleu Lava Métallisé	**Year** 2021	**Upholstery** -
Number of doors 5	**Number of seats** 5	**Generation** -
Engine displacement 1498	**Gearbox type** Automatic	**Engine type** Combustion
Fuel Type Petrol	**Number of gears** 7	**Drivetrain** Front Wheel Drive (FWD)
Max power 110 KW		

Vehicle Equipments

Standard

8 speaker(s)	center armrest rear	center armrest front
keyless door release	multifunction display	Parkpilot system front and rear
airbag driver side/passenger side	kneebag driver side	sidebag front
lashing eyes cargo space sideways	lumbar support seat front left and right	driver assistance system: brake assistant (Audi pre sense front)
roof rails	battery 59 Ah	electronic differential lock (Q2)
glove box illuminated	cargo space cover / roll-up cover	reversing camera
body: 5-door	voice control for infotainment system	Inductive charging tray for mobile devices
air conditioning Climatronic 2-zone	steering column (steering wheel) height-adjustable	steering column (steering wheel) longitudinally adjustable
instrument cluster digital (virtual cockpit)	Electronic Stability Control (ESP)	tire pressure control system
power steering electronically controlled	comfort hands-free equipment Bluetooth	Disques de frein AV (288 mm x 25 mm)
rear seat backrest split/folding	seatback release the rear seat backrest in trunk	wheel arch cover front and rear
wheelbase 2638 mm	Longlife-Service	windshield wiper Aero (flat-blade wiper)
windshield wiper with rain sensor	rear lights LED (crystal glass look)	rear lights LED with dynamic flasher
Interior filter: dust and pollen filter	gasoline particulate filter (GPF)	refrigerant R 1234 YF
roof liner cloth, gray	windshield washer jets heated	tire repair kit
headlight washer system (headlight washer system)	map light	shift/selector lever leather
window lifter electric front + rear	Type of drive: front-wheel drive	Equipment package: parking
comfort package	side window rear and rear window darkened	Winter package
seat heating front	bumper vehicle colour	sun visor right with mirror
sun visor left with mirror	Phonebox	door handles outside vehicle colour
door handles inside chrome-plated	power outlet (12V outlet) front	power outlet (12V outlet) in trunk/load space
headlight LED	model refinement	radio reception digital (DAB+)
exterior mirror vehicle colour	interior mirror with automatic dimming	seat front right height-adjustable

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

seat front left height-adjustable	SmartLink (Apple CarPlay and Android Auto)	Isofix mounts for child seat at rear seat
traction control system (ASR)	audio system Bolero with touchscreen	head airbag system (Sideguard)
antilock braking system (ABS)	driver assistance system: safety system SYNC with automatic emergency call	headlight assist with day/night sensor
driver assistance system: hill-start assist (Hill-Holder)	driver assistance system: collision warning system with brake function	driver assistance system: multi-collision brake (Multi Collision Brake)
start/stop system	VarEq-méthode Equipement Style	central locking system
storage bag at front seatbacks	glazing tinted	steering wheel (leather - 2-spoke) with multiple function and shift function
Wireless SmartLink	licence plate illumination LED	

Optional

anti-theft warning system with interior scanning / inclination monitoring	generator 140 A	dual-tone horn
chrome strips at side windows	transmission 7-speed - dual-clutch transmission S-tronic	suspension raised
trailer coupling with stability control	interior equipment decorative trim inserts aluminium Cross Brushed	infotainment package 1
engine hood insulation	Light-alloy rims	Moteur 1,5 litre(s) - 110 kW 16V TSI ACT Catalyseur (DPCA)
low emissions according to emission standard Euro 6d	convenience opening for electr. liftgate/lid	windshield heated
metallic paintwork	Plaquettes/Garnitures de frein avec témoin d'usure	power outlet 230V
multi-media interface USB (type C) and USB charging port front	front fog lights LED with cornering lights	headlight leveling control
exterior mirror electrically adjustable, heated + folding, with automatic dimming and Memory	seat covers/upholstery: cloth/leather	seat heating front and rear
audio navigation system Columbus	driver assistance system: automatic distance control (ACC incl. Stop&Go function) with periphery observation system (Front assist)	driver assistance system: driving-profile selection
ambient lighting LED		

Statement details

Inspection loc	Statement date	Inspection approval date
PARC HÖDLMAYR TONGEREN	24/09/2026	25/09/2026

Control



Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Bonnet / -	Paint etching	Repair


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

002	Personal Data / -	Non Compliant	Carry out




003	Roof / -	Paint etching	Polishing

004	Floor mat / Front Left	Worn Out	Acceptable



005	Interior complete / -	Stained	Cleaning



006	Windscreen / - Rain sensor : Yes	Chip	Acceptable




All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Loose Items

- [x] Conformity certificate
- [x] Registration certificate
- [x] Registration certificate owner
- [x] Card key
- [x] Compressor tyre repair kit
- [x] Spare Key
- [x] User manual
- [x] Rear parcel shelf
- [x] Document holder

Main set of tyres

Front Left	CONTINENTAL	215/55/17 Summer	6 mm
Front Right	CONTINENTAL	215/55/17 Summer	6 mm
Back Left	GOODYEAR	215/55/17 Summer	7 mm
Back Right	GOODYEAR	215/55/17 Summer	7 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment



Front right




Odometer




Navigation


Spare Tyre




Vin


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other




Other



Other



Bonnet / - / Paint etching



Bonnet / - / Paint etching




Personal Data / - / Non Compliant



Personal Data / - / Non Compliant



Roof / - / Paint etching



Roof / - / Paint etching



Floor mat / Front Left / Worn Out



Interior complete / - / Stained



Windscreen / - / Chip



Windscreen / - / Chip

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.