



CITROËN Berlingo Talla M BlueHdi 100 S&S LIVE PACK combi 75kW 4P manual: 8973-MKB

Vinnumber:	VR7EFYHT2PN551844	Versionname:	
First Registrationdate:	30/08/2023	Fiscalpower:	0
Expertise Mileage:	80568	Power Kw:	
Bodytype:	Transporter	Body colour	White
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Light Commercial Vehicle		
Registration Certificate Car (BE)	No		

Options

Number of keys total	1	Radio
Number keys remote	1	Luggage cover
Windows electric F		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of climate control	Manual climate control	

Tyres

205/60/16/96 V				
Summer tyres:	Fr.L.	Cooper: 6 mm	Fr.R.	Cooper: 6 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/60 R 16 96 V
Tyre size FR				205/60 R 16 96 V
Tyre size RL				205/60 R 16 96 V
Tyre size RR				205/60 R 16 96 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				1957075
Tyre make FR				1957075
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	No
Interior, Dirty, Cleaning	



Armrest F M, Broken, Replace



Door panel FR, Scratch(es), Replace



Door panel RR, Scratch(es), Replace



Door panel RL, Scratch(es), Replace



Seat cover FL, Burned, Replace



Registration document, Missing, Repair/replace (lump sum)



Ignition key, Missing, Repair/replace (lump sum)



Wheel cover FL, Scratch(es), Acceptable



Outside rear-view mirror housing L, Scratch(es), Paint



Side wall RL, Dent(s), Repair and paint (complete)



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Bumper spoiler F, Broken, Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Paint




Outside rear-view mirror housing R, Scratch(es), Acceptable



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Wheel cover FR, Scratch(es), Replace



Wheel cover RR, Scratch(es), Acceptable



Tyre repair kit, Missing, Repair/replace (lump sum)



Internal boot lining R, Scratch(es), Replace



Internal boot lining L, Scratch(es), Replace



Rear panel, Dent(s) and scratch(es), Repair and paint (complete)



Boot door panel RR, Scratch(es), Paint



Bumper R, Scratch(es), Paint



Tyres, No damage, Check

