

2EDE315

2EDE315 · ST-line 2.5i pHEV 225pk 165kw HF45 aut · 27 November 2025 · Zaventem (BE)

Specifications

License Plate Number	2EDE315	Fuel Type	Hybrid Gasoline
Manufacturer	FORD	VIN	WFOFXXWPMHPS57935
Model	Kuga	Cylinder Capacity	2.488 ^{cm3}
Model Versions	ST-line 2.5i pHEV 225pk 165kw HF45 aut	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	04-09-2023
Color	Grey	Odometer	78.779 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Black
KW	112	Number Headrests	5

Images





Accessories

ABS	Electrically adjustable exterior mirrors
Airbags	
Alloy wheels	Fog lights
Audio System	Front & rear parking sensors
Automatic air conditioning	Leather steering wheel
Bluetooth car kit	Navigation system
Central door locking	Rear view camera
Centre armrest	Roller cover / parcel shelf
Cruise control	Seat heating
Electric rear windows	
Electric windows front	Steering wheel multifunction
Electrically adjustable driver's seat	Steering wheel - Heated
	Windscreen - Heated

Condition

Condition exterior Adequate

Last Maintenance Unknown

Condition interior Adequate

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 ^{mm}	Goodyear	225 ^{mm}	60 ^{mm}	18 ^{inch}	All Season
Rear Left	6 ^{mm}	Goodyear	225 ^{mm}	60 ^{mm}	18 ^{inch}	All Season
Front Right	4 ^{mm}	Goodyear	225 ^{mm}	60 ^{mm}	18 ^{inch}	All Season
Rear Right	6 ^{mm}	Goodyear	225 ^{mm}	60 ^{mm}	18 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part

Reardoor - Left



Damage Type

Scratch(es)

Repair Type

Spray

Acceptable

No



Damage Part

Frontdoor - Left



Damage Type

Scratch(es)

Repair Type

Spray


Acceptable

No



Damage Part

Hood



Damage Type

Stonechipping

Repair Type

Acceptable

Acceptable

Yes



Damage Part
Bumper - Front



Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Overfender



Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Alloy - Right Front



Damage Type
Damaged

Repair Type
Rim repair

Acceptable
No



Damage Part
Reardoor - Right



Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Frontdoor - Right



Damage Type
Small dent(s)



Repair Type
Restyle / Touch-up

Acceptable
No



Damage Part
Bumper - Rear



Damage Type
Scratch(es)



Repair Type
Spray

Acceptable
No



Damage Part

Tailgate



Damage Type

Scratch(es)



Repair Type

Spray

Acceptable

No



Damage Part

380v Charging cable

Damage Type

Missing

Repair Type

Replace

Acceptable

No



Damage Part

230v Charging cable

Damage Type

Missing

Repair Type

Replace

Acceptable

No