DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	W0V7H9EN3 R4006032	Registration date	29/02/2024	Exterior Color	Unknown
Brand	OPEL	Licence Plate	Y-905 859	Odometer	19 897 km
Model	CROSSLAND 1.5 Diesel 81kW Elegance				

Inspection Details

Arrival Date	08/07/2026	Inspection ID	7072368	Inspection date	22/07/2026
Assign Date	08/07/2026	Fleet owner	Leasys Privat Leasing	Inspection loc.	Leasys Hubmotion Gifhorn

















Generic equipment

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓
Radio user manual	✓


Technical Document

User manual	✓
Log books	✓
Spare key	✓
Key	✓
Warranty booklet	✗
Service	✗

Tyres

Bridgestone 195/60/16 H All seasons 5.0 mm

Bridgestone 195/60/16 H All seasons 5.0 mm



Bridgestone 195/60/16 H All seasons 5.0 mm

Bridgestone 195/60/16 H All seasons 5.0 mm

Exception / Damage

1



Part	Warranty booklet	Repair Time	-	Part Cost	20.00€
Position	-	Repair Cost	-	Gross Cost	20.00€
Damages	Missing	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	**Net Cost**	**20.00€**

2



Part	Service	Repair Time	-	Part Cost	300.00€
Position	-	Repair Cost	-	Gross Cost	300.00€
Damages	Missing	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	**Net Cost**	**300.00€**

3



Part	Service 2	Repair Time	-	Part Cost	300.00€
Position	-	Repair Cost	-	Gross Cost	300.00€
Damages	Missing	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	**Net Cost**	**300.00€**

4

Part	Bumper	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Scratched	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

5

Part	Bonnet	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Scratched	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

6

Part	Windscreen	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Stone impact	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

7



Part	Door	Repair Time	0.30	Part Cost	-
Position	Front right	Repair Cost	42.00€	Gross Cost	42.00€
Damages	Sticker marked	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Sticker removal	Flat Rate	42.00€	**Net Cost**	**42.00€**

8



Part	Door	Repair Time	0.70	Part Cost	-
Position	Back right	Repair Cost	98.00€	Gross Cost	323.00€
Damages	Scratched	Paint Time	1.50	Depreciation %	15.00%
Severity	-	Paint cost	225.00€	Depreciation	- 48.45
Repair mode	Repair	Flat Rate	-	**Net Cost**	**274.55€**

9



Part	Wing	Repair Time	2.40	Part Cost	-
Position	Back right	Repair Cost	336.00€	Gross Cost	411.00€
Damages	Dented	Paint Time	0.50	Depreciation %	15.00%
Severity	-	Paint cost	75.00€	Depreciation	- 61.65
Repair mode	Repair	Flat Rate	-	**Net Cost**	**349.35€**

10



Part	Tailgate / Boot door	Repair Time	0.30	Part Cost	-
Position	Back	Repair Cost	42.00€	Gross Cost	42.00€
Damages	Sticker marked	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Sticker removal	Flat Rate	42.00€	**Net Cost**	**42.00€**

11



Part	Door	Repair Time	0.30	Part Cost	-
Position	Front left	Repair Cost	42.00€	Gross Cost	42.00€
Damages	Sticker marked	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Sticker removal	Flat Rate	42.00€	**Net Cost**	**42.00€**

12



Part	Diamond Cut rim 16"	Repair Time	-	Part Cost	-
Position	Front right	Repair Cost	-	Gross Cost	-
Damages	Scratched	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

13

Part	Paint preparation	Repair Time	-	Part Cost	-
Position	-	Repair Cost	-	Gross Cost	195.00€
Damages	-	Paint Time	1.30	Depreciation %	15.00%
Severity	-	Paint cost	195.00€	Depreciation	- 29.25
Repair mode	Paintworks	Flat Rate	-	**Net Cost**	**165.75€**

Summary Inspection

Gross Price	1,675.00€	Depreciation	-139.35€	Net Price	1,535.65€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	140.00€	4.00	560.00€	11.63 %	-65.10€	494.90€
Paintwork	150.00€	2.00	300.00€	15.00 %	-45.00€	255.00€
Paint preparation	150.00€	1.30	195.00€	15.00 %	-29.25€	165.75€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	620.00€	-	-	620.00€
Flat Rate	-620.00€	-	-	-620.00€