


MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia											
				Policyholder				Opposite party				Opposite party company									
				Operation 2026		Claim number			Code / Agency				Date accident 22/06/2026								
				Expert code		Adjuster code			Policy number				Injured person can recover the VAT								
Date assignment 22/06/2026		Date first survey 30/06/2026		Place Rho		C/O VAR		Repairs TO START		Photo		Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)														Formerly plate							
Lessee / Co-owner														Date of overhaul							
Vehicle (Brand - Model - Version) VOLKSWAGEN TIGUAN 2.0 TDI SCR 110KWR-Line DSG								Plate GK024FJ		Vin Chassis WVGZZZ5NZNW513814				First Registration 27/04/2022							
Usage status NON CONOSCIUTO		Km 59349		Tyres % 90		Color Nero		Type of enamel PASTEL/DOUBLE				Consistency of damage YES		Type of Expert's report NOT DEFINITIVE							
Equipment																					
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0										Wheelbase		Seats No. 0		Axles 0	
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses															
Damaged items / restoration operations								SR		LA		VE		ME		D.M. S.C.		Costs of spare parts * (VAT excluded)			
1 Codice Ricambio Pneumatico								S		S		S									
1 5NA853835C2ZZ Trim of rear bumper								S		S		S									
1 5NA854819J9B9 Rear wheel arch trim L								S		S		S									
1 5NA867703B82V Internal side cladding of rear hatch L								S		S		S									
1 5NA867704B82V Internal side cladding of rear hatch R								S		S		S									
1 5NA817101 Roof								M		M		M									
1 5NA823031L Front bonnet								L		L		L									
1 5NA827025M Rear hatch								L		L		L									
1 5NA807421GRU Rear bumper upper part								L		L		L									
3 Codice Ricambio Rett. cerchi lega R20																					

New for old value (N)	Remarks Pneum. INV. Good Year 255/40 R20. Vhl sporco, grandinato. Manutenzione in scadenza.
-----------------------	--

ALPHABET

Telaio WVGZZZ5NZNW513814

GK024FJ

VOLKSWAGEN TIGUAN 2.0 TDI SCR 110KWR-Line DSG sports utility vehicle 150CV 5P automatico

Current Odo (Time of Ma	Maintenance Request	Service Type Descriptio	Maintenance Job Description
13.241	12/04/23	Tagliando a 15 000 km	Tagliando a 15 000 km
28.029	20/03/24	Maintenance	Additivo FAP
30.158	12/06/24	Tagliando a 30 000 km	Tagliando a 30 000 km
44.393	11/06/25	Tagliando a 45 000 km	Tagliando a 45 000 km