



RENAULT CLIO: GD-743-PE

Vinnumber:	VF1RJA00968305726	Versionname:	RENAULT CLIO Business E-Tech hybride 140 -21N
First Registrationdate:	15/12/2021	Fiscalpower:	VP [5P] bva 6-140CH-5cv (bi-corps)
Expertise Mileage:	105338	Power Kw:	103
Bodytype:	Berline	Body colour:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Hybrid	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Seat cover lining	Lining Other
Steering wheel leather			
Type of climate control	Autom climate control		

Tyres

	195/55/16/87 V			
Summer tyres:	Fr.L.	Bridgestone: 60%	Fr.R.	Bridgestone: 55%
	Re.L.	Goodyear: 25%	Re.R.	Goodyear: 25%
Tyre profile depth FL				4.3
Tyre profile depth FR				4.5
Tyre profile depth RL				6.6
Tyre profile depth RR				6.4
Tyre size FL				195/55 R 16 87 V
Tyre size FR				195/55 R 16 87 V
Tyre size RL				195/55 R 16 87 V
Tyre size RR				195/55 R 16 87 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)



Interior, Stain, Chemical cleaning



Door panel RL, Scratch(es), Replace



Wheel cover FR, Broken, Replace



Outside rear-view mirror housing L, Scratch(es), Paint



Door RL, Dent(s), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Replace



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Bumper F, Scratch(es), Paint





Door FR, Scratch(es), Paint



Outside rear-view mirror housing R, Scratch(es), Paint



Bumper R, Scratch(es), Polish



Boot lid covering R, Scratch(es), Replace



Bodywork, Not original part, Remove lettering



Historique Maintenance

Immatriculation: **GD-743-PE** Date de 1ère immatriculation: **15/12/2021**

Modèle: **Renault CLIO Business E-Tech hybride 140 -21N VP [5P] bva 6-140CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
25/11/2025	85.658	FLEET SOLUTIONS FRANCE	REPLACEMENT PNEUS ETE
21/11/2025	85.228	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
28/04/2025	74.614		DIAG
	0		BALAIS ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		TELECHARGEMENT CALCULATEUR
	0		DIVERS CARROSSERIE
	0		REVISION ET CLIM
	0		LIQUIDE DE FREIN
10/04/2025	73.657	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
	0		PERMUTATIONS PNEUS
	0		GARDIENNAGE
17/12/2024	65.777	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
	0		GARDIENNAGE
14/08/2024	56.173	CONTITRADE FRANCE	REPARATION DE ROUE
07/06/2024	51.688		REVISION ET CLIM ET AIR ET BOUGIES
	0		RECYCLAGE
24/05/2024	50.247	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
	0		GARDIENNAGE
08/02/2024	44.077		PILE DE CLE RPLT
25/01/2024	43.359	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS HIVER
	0		REPLACEMENT PNEUS HIVER
26/06/2023	29.253	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
22/06/2023	29.096		BALAIS ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		REVISION ET CLIM
	0		RECYCLAGE
30/12/2022	15.189	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS 4 SAISONS