



**RENAULT CLIO: GJ-321-MA**

Vinnumber:	<b>VF1RJA00269640143</b>	Versionname:	<b>RENAULT CLIO Business TCe 90 -21N VP [5P] bvm 6-90CH-5cv (bi-corps)</b>
First Registrationdate:	<b>20/09/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>49764</b>	Power Kw:	<b>66</b>
Bodytype:	<b>Berline</b>	Body colour:	<b>Light Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Interior colour:	<b>Black</b>
Fueltype:	<b>Petrol</b>	Type of rims (mounted):	<b>Steel</b>
Engine functioning:	<b>Yes</b>	Dashboard color:	<b>Black</b>
Battery functioning:	<b>Yes</b>		
Vehicle running:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Steel</b>		
Category:	<b>Passenger Car</b>		

**Options**

Number of keys total	<b>1</b>	Radio	
Number keys remote	<b>1</b>	Luggage cover	
GPS big screen color		Rear parking sensors	
Windows electric F		Seat cover lining	<b>Lining Other</b>
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	<b>Manual climate control</b>		

**Tyres**

<b>195/55/16/87 H</b>				
Summer tyres:	Fr.L.	<b>Kleber: 40%</b>	Fr.R.	<b>Kleber: 50%</b>
	Re.L.	<b>Bridgestone: 55%</b>	Re.R.	<b>Bridgestone: 60%</b>
Tyre profile depth FL				<b>5.7</b>
Tyre profile depth FR				<b>5.0</b>
Tyre profile depth RL				<b>4.5</b>
Tyre profile depth RR				<b>4.2</b>
Tyre size FL				<b>195/55 R 16 87 H</b>
Tyre size FR				<b>195/55 R 16 87 H</b>
Tyre size RL				<b>195/55 R 16 87 H</b>
Tyre size RR				<b>195/55 R 16 87 H</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>2479</b>
Tyre make FR				<b>2479</b>
Tyre make RL				<b>255</b>
Tyre make RR				<b>255</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Remote ignition key, Missing, Repair/replace (lump sum)			



**Wheel cover FL, Broken, Replace**



Door RL, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Paint



Outside rear-view mirror housing R, Scratch(es), Polish



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Paint



Bumper R, Scratch(es), Acceptable



# Historique Maintenance

Immatriculation: **GJ-321-MA**Date de 1ère immatriculation: **20/09/2022**Modèle: **Renault CLIO Business TCe 90 -21N VP [5P] bvm 6-90CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
22/04/2026	49.609	GARAGE DES LICES	BALAI ESSUIE GLACE AR
	0		REVISION
	0		FILTRE CLIM RPLT
	0		LIQUIDE DE FREIN
	0		BALAISS ESSUIE GLACE AV
	0		RECYCLAGE
06/05/2025	41.028		BALAI ESSUIE GLACE AR
	0		REVISION
	0		PLAQUETTES AV RPLT
	0		GEOMETRIE CTRL
	0		BALAISS ESSUIE GLACE AV
03/05/2024	28.909	SYLVER FOX	REVISION
20/11/2023	21.977	SYLVER FOX	SERENITE