



RENAULT CLIO: GK-268-LP

Vinnumber:	VF1RJA00469640273	Versionname:	RENAULT CLIO Business E-Tech hybride 140 -21N
First Registrationdate:	9/11/2022	Fiscalpower:	VP [5P] bva 6-140CH-5cv (bi-corps)
Expertise Mileage:	112262	Power Kw:	103
Bodytype:	Berline	Body colour	White
Gearbox:	Automatic	Paint type	Opaque
Transmission:	Front	Interior colour	Dark Grey
Fueltype:	Hybrid	Type of rims (mounted)	Steel
Engine functioning	Yes	Dashboard color	Black
Battery functioning	Yes		
Vehicle running	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Steel		
Category	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Headlights Xenon/LED/Laser	
Windows electric F		Rear parking sensors	
Cruise Control		Seat cover lining	Lining Other
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Manual climate control		

Tyres

	195/55/16/87 H			
Summer tyres:	Fr.L.	Goodyear: 80%	Fr.R.	Goodyear: 80%
	Re.L.	Michelin: 35%	Re.R.	Michelin: 35%
Tyre profile depth FL				3.1
Tyre profile depth FR				3.1
Tyre profile depth RL				6.0
Tyre profile depth RR				5.8
Tyre size FL				195/55 R 16 87 H
Tyre size FR				195/55 R 16 87 H
Tyre size RL				195/55 R 16 87 H
Tyre size RR				195/55 R 16 87 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)



Armrest F M, Broken, Replace



Interior, Stain, Cleaning



Seat cover R, Unclashed, Dismount/Mount



Roof liner, Burned, Smart repair



Tyre FR, Out of tolerance, Replace



Tyre FL, Out of tolerance, Replace



Wing FL, Dent(s), Acceptable



Door FL, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)





Headlight R, Scratch(es), Acceptable



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill R, Dent(s), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Wing FR, Dent(s) and scratch(es), Replace and paint



Outside rear-view mirror housing R, Scratch(es), Acceptable



Luggage compartment cover, Missing, Replace



Rear upper boot lining, Scratch(es), Replace



Bumper R, Scratch(es), Paint



Bodywork, Not original part, Remove lettering



Historique Maintenance

Immatriculation: **GK-268-LP** Date de 1ère immatriculation: **09/11/2022**

Modèle: **Renault CLIO Business E-Tech hybride 140 -21N VP [5P] bva 6-140CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
13/05/2026	109.811	PERPIGNAN AVENIR AUTOMOBILE (PAA)	RECYCLAGE
	0		REVISION ET CLIM
	0		DISQUES PLAQUETTES AV RPLT
	0		BALAI ESSUIE GLACE AR
	0		BALAI ESSUIE GLACE AV
	0		LIQUIDE DE FREIN
03/12/2025	89.182	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS HIVER
	0		REMPLACEMENT PNEUS HIVER
24/07/2025	74.064		REVISION ET CLIM ET AIR ET CARBURANT
18/04/2025	53.444		RETROVISEUR G RPLT
05/08/2024	50.897	PROFIL PLUS	FERMETURE DOSSIER TECHNIQUE
05/08/2024	50.897	PROFIL PLUS	REMPLACEMENT PNEUS 4 SAISONS
04/06/2024	48.027	RENAULT RETAIL GROUP	CHAINES NEIGE RPLT
07/11/2024	32.705	NORAUTO SAS (PRODUIT SPE)	REMPLACEMENT PNEUS 4 SAISONS
22/09/2023	30.000	RENAULT RETAIL GROUP	REVISION