



Ford Kuga: T035KH

| | | | |
|-------------------------|--------------------------|-------------------------|---|
| Vinnumber: | WF0FXXWPMHPL10820 | Versionname: | Kuga 2.5 165kW PHEV ST-Line X automaat |
| First Registrationdate: | 30/06/2023 | Fiscalpower: | |
| Expertise Mileage: | 177640 | Power Kw: | 112 |
| Bodytype: | | Body colour: | Chrome Blue Trendy Metaallak |
| Gearbox: | Automatic | Paint type: | Metallic |
| Transmission: | | Type of rims (mounted): | Aluminium |
| Fueltype: | Hybrid Petrol | Parking lot: | 618 |
| Number of seats: | 5 | | |
| Type of rims (mounted): | Aluminium | | |
| Maintenance needed: | No | | |

Options

| | | |
|-----------------------|----------|----------------------|
| Number of keys total | 2 | Lining semi-leather |
| GPS | | Lining Alcantara |
| Autom climate control | | Rear parking sensors |
| Radio multimedia | | Tow bar removable |
| | | Hook |
| | | Rear view camera |

Tyres

| Location | Position | Measures | Depth | Make | Type |
|----------|----------|-------------------------------------|--------|------------|--------|
| Front | Left | 225 / 60 / 18 / 104 / W / Aluminium | 5,5 mm | Vredestein | Summer |
| | Right | 225 / 60 / 18 / 104 / W / Aluminium | 5,5 mm | Vredestein | Summer |
| Rear | Left | 225 / 60 / 18 / 104 / W / Aluminium | 6,0 mm | Vredestein | Summer |
| | Right | 225 / 60 / 18 / 104 / W / Aluminium | 5,8 mm | Vredestein | Summer |

Assistance equipment

| | |
|--|----------|
| Number of charging cables (rapid charge) | 1 |
|--|----------|

Door RL, Scratch(es), Polish



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)



Wing RR, Scratch(es), Polish



Door trim FR, Scratch(es), Replace and paint



Bumper R, Scratch(es), Repair and paint (complete)



| | |
|-----------------------|---|
| Kenteken | T035KH |
| Merk Model | Ford Kuga 2.5 165kW PHEV ST-Line X automaat |
| Brandstofsoort | Benzine |
| Datum deel1 | 30-06-23 |

| Datum reparatie | Kilometerstand | Reparatie omschrijving |
|-----------------|----------------|-----------------------------------|
| 31-03-26 | 168.016 | Onderhoudsbeurt |
| 20-11-25 | 144.136 | Onderhoudsbeurt |
| 20-11-25 | 144.136 | Remvloeistof |
| 10-11-25 | 142.051 | Reparatie band(en) |
| 15-07-25 | 117.647 | Onderhoudsbeurt |
| 15-07-25 | 117.647 | Ruitenwischerblad(en) achterzijde |
| 15-07-25 | 117.647 | Ruitenwischerblad(en) voorzijde |
| 01-07-25 | 114.991 | Laadstroommeter |
| 05-03-25 | 94.963 | Onderhoudsbeurt |
| 26-09-24 | 70.952 | Onderhoudsbeurt |
| 19-06-24 | 52.630 | Motorolie verversen |
| 19-06-24 | 52.630 | Sleutelbatterij |
| 12-01-24 | 31.943 | Onderhoudsbeurt |
| 12-01-24 | 31.943 | Ruitenwischerblad(en) voorzijde |
| 12-01-24 | 31.943 | Sleutelbatterij |
| 21-11-23 | 25.939 | Motorolie verversen |