

INSPECTION REPORT



End of contract

GENERAL INFO

File	314985
License plate	2CMN232
Vehicle identification number	WAUZZZF53PA009734
Dossier	2022080049
Make	Audi A5 SB 30 TDi 100kW Bu.Es.
Mileage	172048
First registration	16/09/2022
client availability date	22/06/2026
inspectionDate	01/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	Y
18	Bumper Front / Spoiler / Replace	N
80	Door Front Left // Smart Repair Small	Y
104	Door Rear Left // Repair & Painting	N
114	Wing Rear Left // Repair & Painting	N
153	Rear Bonnet // Painting	Y
210	Door Front Right // Smart Repair Small	Y
234	Wing Front right // Repair & Painting	N
311	Wheel Alloy Front Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N

Damage Pictures



Rear Bonnet // Painting-scratch



Door Front Right // Smart Repair Small-scratch





Wheel Alloy Front Right // Repair-scratch



Bumper Front // Smart Repair Large-scratch



Wheel Alloy Front Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch



Wheel Alloy Rear Right // Repair-scratch



Door Rear Left // Repair & Painting-scratch + dent



Wing Front right // Repair & Painting-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Bumper Front / Spoiler / Replace-cracked