



Volkswagen Tiguan (KKL): 1YQL231

Vinnumber:	WVGZZZ5NZMM000719	Versionname:	Tiguan Allspace Comfortline 1.5TSi ACT 150pk/cv 5p DSG7
First Registrationdate:	5/11/2020	Fiscalpower:	
Expertise Mileage:	128746	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	16100.0		
Maintenance	494 dagen		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	215/65/17/99 V			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL	5.0			
Tyre profile depth FR	5.0			
Tyre profile depth RL	3.0			
Tyre profile depth RR	4.0			
Tyre size FL	215/65 R 17 99 V			
Tyre size FR	215/65 R 17 99 V			
Tyre size RL	215/65 R 17 99 V			
Tyre size RR	215/65 R 17 99 V			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	256			
Tyre make FR	256			
Tyre make RL	256			
Tyre make RR	256			

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Instrument panel, complete, Scratch(es), Acceptable



Seat cover FL, Worn, Check



Door panel RR, Scratch(es), Acceptable



Interior covering A pillar L, Scratch(es), Acceptable



Roof liner, Stain, Cleaning



Interior covering A pillar R, Scratch(es), Acceptable



Backrest cover FR, Scratch(es), Acceptable



Interior, Damaged, Acceptable



Bumper spoiler F, Scratch(es), Acceptable



Bumper F, Scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Wing FL, Dent(s) and scratch(es), Acceptable



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Dent(s) and scratch(es), Acceptable





Step L, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Interior covering C pillar L, Scratch(es), Acceptable



Interior covering C pillar R, Scratch(es), Acceptable



Rubber seal for boot lid, Broken, Replace



Bumper R, Scratch(es), Acceptable





Bumper trim R, Scratch(es), Acceptable



Tailgate / Boot, Dent(s), Paintless dent repair




Rear light R tailgate, Scratch(es), Acceptable



Wheel aperture RR, Dent(s) and scratch(es), Spot repair




Door RR, Dent(s) and scratch(es), Acceptable



Alloy rim RR polished, Chemical polution, Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Step R, Dent(s), Acceptable



Kenteken	1YQL231
Merk Model	Volkswagen Tiguan Allspace Comfortline 1.5TSi ACT 150pk/cv 5p DSG7
Brandstofsoort	Benzine
Datum deel1	11/5/20

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
11/28/25	114,783	Inspectie met olie vervanging (vast in	Uitvoeren
11/28/25	114,783	klein materiaal	
11/28/25	114,783	luchtfILTER interieur	Vervangen
11/28/25	114,783	remvloeistof	Vervangen
11/28/25	114,783	ruitenwisservloeistof	Bijvullen/-laden
11/28/25	114,783	versnellingsbakolie	Vervangen
7/15/25	104,271	accu	Vervangen
7/15/25	104,271	controle niveaus	Uitvoeren
7/15/25	104,271	klein materiaal	
10/9/24	85,307	Inspectie met olie vervanging (vast in	Uitvoeren
10/9/24	85,307	klein materiaal	
10/9/24	85,307	luchtfILTER	Vervangen
10/9/24	85,307	remblokken achter	Vervangen
10/9/24	85,307	remblokken vooraan	Vervangen
10/9/24	85,307	ruitenwisserrubber achter	Vervangen
10/9/24	85,307	ruitenwisserrubber vooraan	Vervangen
10/9/24	85,307	ruitenwisservloeistof	Bijvullen/-laden
10/9/24	85,307	slang koelsysteem	Vervangen
10/9/24	85,307	waterafvoer open dak	Reinigen
9/18/23	58,092	controle niveaus	Uitvoeren
9/18/23	58,092	klein materiaal	
9/18/23	58,092	navigatiesysteem	Repareren
9/18/23	58,092	olie bijvullen	Bijvullen/-laden
9/18/23	58,092	ruitenwisservloeistof	Bijvullen/-laden
7/7/23	51,557	bougie	Vervangen
7/7/23	51,557	Inspectie met olie vervanging (vast in	Uitvoeren
7/7/23	51,557	klein materiaal	
7/7/23	51,557	koelwater vloeistof	Bijvullen/-laden
7/7/23	51,557	luchtfILTER interieur	Vervangen
7/7/23	51,557	navigatiesysteem	
7/7/23	51,557	remvloeistof	Vervangen
7/7/23	51,557	ruitenwisserrubber vooraan	Vervangen
7/7/23	51,557	ruitenwisservloeistof	Bijvullen/-laden
7/7/23	51,557	waterafvoer open dak	Reinigen