



Polestar 2:

Vinnumber:	LPSVSEGEKNL077829	Versionname:	
First Registrationdate:	5/05/2022	Fiscalpower:	
Expertise Mileage:	110469	Power Kw:	
Bodytype:		Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2819
Fueltype:	Electric		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Seats electric F L:	
Cruise Control:		Seats electric F R:	
Steering wheel multifunctional:		Panoramic roof:	
Seats F heated:		Luggage cover:	
Radio multimedia:		Front parking sensors:	
Type of headlighting:	Headlighting LED	Rear parking sensors:	
Type of GPS:	GPS big screen color	Type of Tow bar:	No Tow bar
Type of Lining:	Lining semi-artificial leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Tyres

	245/45/19/92 H			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL:				5.0
Tyre profile depth FR:				5.0
Tyre profile depth RL:				5.0
Tyre profile depth RR:				5.0
Tyre size FL:				245/45 R 19 92 H
Tyre size FR:				245/45 R 19 92 H
Tyre size RL:				245/45 R 19 92 H
Tyre size RR:				245/45 R 19 92 H
Tyre type FL:				Summer
Tyre type FR:				Summer
Tyre type RL:				Summer
Tyre type RR:				Summer
Tyre make FL:				261
Tyre make FR:				261
Tyre make RL:				261
Tyre make RR:				261

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	1		
Number of charging cables (rapid charge):	1		

Total cost ex VAT:	1776,86
Door panel RL, Scratch(es), Smart repair:	116,69



Bonnet, Chemical polution, Repair and paint (complete) 487,44



Alloy rim RL polished, Scratch(es), Repair and paint (complete) 204,21



Door RL, Scratch(es), Acceptable 0,00




Wing RL, Scratch(es), Acceptable 0,00



Door FL, Scratch(es), Acceptable 0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete) 204,21



Bumper R, Scratch(es), Repair and paint (complete) 355,89



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 204,21



Door RR, Scratch(es), Acceptable 0,00



Alloy rim RR polished, Scratch(es), Repair and paint (complete) 204,21



Bodywork, Not original part, Remove lettering

0,00



Roof, Scratch(es), Acceptable

0,00

