



VOLKSWAGEN GOLF: GL-702-YG

Vinnumber:	WVWZZZCD2PW022072	Versionname:	VOLKSWAGEN GOLF 1.0 eTSI OPF 110 DSG7 Life Business VP [5P] bva 7-110CH-6cv (bi-corps)
First Registrationdate:	31/01/2023	Fiscalpower:	
Expertise Mileage:	83095	Power Kw:	81
Bodytype:	Berline	Body colour:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Interior colour:	Black
Fueltype:	Petrol	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Steering wheel leather		Rear view camera	
Type of climate control	Autom climate control	Seat cover lining	Lining Other

Tyres

	205/55/16/91 V			
Summer tyres:	Fr.L.	Michelin: 25%	Fr.R.	Michelin: 25%
	Re.L.	Michelin: 30%	Re.R.	Michelin: 25%
Tyre profile depth FL				6.5
Tyre profile depth FR				6.5
Tyre profile depth RL				6.3
Tyre profile depth RR				6.4
Tyre size FL				205/55 R 16 91 V
Tyre size FR				205/55 R 16 91 V
Tyre size RL				205/55 R 16 91 V
Tyre size RR				205/55 R 16 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Seat cover FR, Stain, Cleaning



Alloy rim RL, Scratch(es), Repair/replace (lump sum)



Alloy rim FR, Scratch(es), Acceptable



Wheel arch cover FL, Broken, Replace



Wing RL, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Rear bulkhead lining, Scratch(es), Repair/replace (lump sum)



Historique Maintenance

Immatriculation: **GL-702-YG**

Date de 1ère immatriculation: **31/01/2023**

Modèle: **Volkswagen GOLF 1.0 eTSI OPF 110 DSG7 Life Business VP [5P] bva 7-110CH-6cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
14/04/2025	63.388	COURTOISE MOTORS	PLAQUETTES AR RPLT
	0		REVISION
	0		LIQUIDE DE FREIN
	0		BALAI ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		DISQUES PLAQUETTES AV RPLT
12/12/2023	31.720	VELIZY AUTOMOBILES	REVISION
	0		BALAI ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		PILE DE CLE RPLT
	0		PLAQUETTES AV RPLT
	0		FILTRE CLIM RPLT