APPRAISAL REPORT



IDENTIFICATION VEHICLE

Make:	RENAULT
Model / version:	ESPACE
Vin:	VF1RFC00867263388
Plate:	2ARF058
Mileage:	150397
First registration:	18/06/2021
Color:	Gris Titaniu

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book:	
Number of keys:	2
Original key:	✓


PICTURES
















































VIN INFORMATION

Radio	Radio avec système de navigation	Transmission séquentielle
6 rapports	Projecteurs à allumage automatique	Code équipement EA2
Matière : alliage	Lettre repère (J)	Diamètre avant 18
Diamètre arrière 18	Largeur avant 7,5	Largeur arrière 7,5
Diamètre avant 18	Diamètre arrière 18	Hauteur avant 60
Hauteur arrière 60	Indice de vitesse avant V	Indice de vitesse arrière V
Largeur avant 235	Largeur arrière 235	Finition intérieure Harmonie 5
Climatisation arrière	Diesel	1997 cm3
2.00 litres	118 kw	160 ch
Euro 6	Métallisée vernissée	Rétroviseur gauche à réglage mémorisé
Rétroviseur droit à réglage mémorisé	Rétroviseurs rabattables électriques	Rétroviseurs avec éclairage du sol
Garnitures tissu et cuir	Volant cuir	Volant bois
Aide au stationnement avant	Aide au stationnement arrière	Assistance au parking
Caméra avant	Régulateur automatique de la distance	Affichage tête haute
Affichage lecture des panneaux de signalisation	Carte mains libres	Ouverture du coffre électriquement
Pare-brise athermique	Lunette arrière teintée foncée	Vitres portes arrière teintées foncées
Vitres de custode teintées foncées	détecteur de pluie essuie-vitre	Protection piéton
Alerte de distance de sécurité	Alerte franchissement de ligne (AFIL)	Freinage d'urgence assistée autonome (urbain)
Avertisseur d'angle mort	Contrôle pression des pneus	depuis 03.21

période de documentation 2019
phares "Full LED Technology" (LEDH2)
pré-chauffage habitacle (THEPLG)
protection disques de frein av (PRODIS)
éclairage intérieur Ambiente (ECAMH1)
7 places
tableau de bord digital + TFT (MET04)
suspension durcie 1 (TRSEV1)
carte de navigation d'Europe (MAPSUP)
équipement supplémentaire SAN513
Multi-Sense System 1 (MLEXP1)
kit réparation pneus

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	✓	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:		**Fast charging cables:**	

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			Summer	Aluminium	?
Front right	5 mm			Summer	Aluminium	?
Rear left	5 mm			Summer	Aluminium	?
Rear right	5 mm			Summer	Aluminium	?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
2	Windscreen	Crack
3	Inner door sill RR covering	Dent(s) and scratch(es)

Total: 2

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
1	Bodywork	Dent(s) and scratch(es)	✓	✗	✗

Total: 1

DAMAGES DETAILS

2 - Windscreen - Crack





3 - Inner door sill RR covering - Dent(s) and scratch(es)




1 - Bodywork - Dent(s) and scratch(es) - Renta®



























