



Mercedes A

Vinnumber:	WDD1771871J168878	Versionname:	
First Registrationdate:	28/10/2019	Fiscalpower:	
Expertise Mileage:	138621	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2509
Fueltype:	Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather and alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

225/45/18/92 H				
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/45 R 18 92 H
Tyre size FR				225/45 R 18 92 H
Tyre size RL				225/45 R 18 92 H
Tyre size RR				225/45 R 18 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				265
Tyre make FR				265
Tyre make RL				265
Tyre make RR				265

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1600,97
Seat cover FL, Stain, Cleaning	29,16



Bumper F, Scratch(es), Repair and paint (complete)

296,58



Windscreen, Stone chip(s), Replace

0,00



Alloy rim RL polished, Scratch(es), Repair and paint (complete)

204,21



Step L, Dent(s) and scratch(es), Repair and paint (complete)

161,81



Wing FL, Scratch(es), Acceptable

0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete)

204,21



Bumper R, Scratch(es), Repair and paint (complete)

296,58



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

204,21



Wing RR, Dent(s), Acceptable

0,00



Alloy rim RR polished, Scratch(es), Repair and paint (complete)

204,21



Wing RR, Repaired, Acceptable

0,00

