



PEUGEOT 2008

Immatriculation	-
VIN	VR3USHNKKNJ710060
Kilométrage	38 328 km
Première immatriculation	16/09/2022
Couleur carrosserie	Gris Foncé

DÉTAILS DE L'INSPECTION

Adresse d'inspection

Adresse d'inspection

INFORMATIONS SUR LE VÉHICULE

Marque	PEUGEOT	Type de carrosserie	SUV
Modèle	2008	Nbre portes	5
VIN	VR3USHNKKNJ710060	Nbre sièges	5
Première immatriculation	16/09/2022	Transmission	Avant
Kilométrage	38 328 km	Couleur intérieur	Noir
Catégorie	Vehicule particulier	Couleur carrosserie	Gris Foncé

DOCUMENTS ET CLÉS

Carnet d'entretien	Non	Manuel d'utilisation	Non
Nbre clés total	1	Certificat immatriculation (original)	N/A
Nbre clés télécommandes	1	Certificat immatriculation (original)	Non

OPTIONS

Batterie fonctionnante	Oui	Cache bagages	Oui
Moteur fonctionnant	Oui	Compresseur	Oui
Véhicule roulant	Oui	Kit réparation	Oui
Niveau carburant	0	Nature de peinture	Metallisé
Camera de recul	Oui		

PNEUS

Pneus montés


Emplacement	Position	Profondeur des sculptures	Fabricant	Dimensions	Type de pneu	Type de jantes	Runflat
Avant	Gauche	5,9 mm	BF Goodrich	215/60 R 17 96 H	Eté	Aluminium	Non
Avant	Droite	6,0 mm	BF Goodrich	215/60 R 17 96 H	Eté	Aluminium	Non
Arrière	Gauche	4,0 mm	Continental	215/60 R 17 96 H	Eté	Aluminium	Non
Arrière	Droite	4,0 mm	Continental	215/60 R 17 96 H	Eté	Aluminium	Non

DAMAGES



Wing RR

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



Door RL

Damage type	Dent(s) and scratch(es)
Repair mode	Repair and paint (complete)



Tailgate / Boot

Damage type	Dent(s) and scratch(es)
Repair mode	Repair and paint (complete)



Door RR

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



Bumper F

Damage type	Scratch(es)
Repair mode	Repair and paint (complete)





Roof pillar L

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



Remote ignition key (no insert)

Damage type	Missing
Repair mode	Repair/replace (lump sum)



Bumper moulding F

Damage type	Broken
Repair mode	Replace



Wing trim FR

Damage type	Deformed / Strained
Repair mode	Replace



Bumper moulding R

Damage type	Scratch(es)
Repair mode	Paint



Malfunction indicator

Damage type	Blinking
Repair mode	Check



Door FR

Damage type	Scratch(es)
Repair mode	Polish

COMMERCIAL PHOTOS

