



**Volkswagen ID.4: L188JG**

Vinnnumber:	<b>WVGZZZE2ZMP009017</b>	Versionname:	<b>ID 4 Outgoing 150kW / 77kWh 1ST Automaat</b>
First Registrationdate:	<b>28/06/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>112065</b>	Power Kw:	<b>150</b>
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:		Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Electric</b>	Parking lot:	<b>1086</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>No</b>		

**Options**

Number of keys total	<b>2</b>	Lining semi-leather
GPS		Lining Alcantara
Autom climate control		Rear parking sensors
Radio multimedia		Hook
		Rear view camera

**Tyres**

Location	Position	Measures	Depth	Make	Type
Front	Left	255 / 45 / 20 / 101 / T / Aluminium	6,0 mm	Continental	Summer
	Right	255 / 45 / 20 / 101 / T / Aluminium	4,5 mm	Continental	Summer
Rear	Left	255 / 45 / 20 / 101 / T / Aluminium	4,8 mm	Continental	Summer
	Right	255 / 45 / 20 / 101 / T / Aluminium	6,2 mm	Continental	Summer

**Assistance equipment**

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>1</b>

**Wing FL, Scratch(es), Repair and paint (complete)**



**Door FL, Scratch(es), Repair and paint (complete)**



**Door RL, Dent(s) and scratch(es), Repair and paint (complete)**



**Wing RL, Scratch(es), Repair and paint (complete)**



Bonnet, Scratch(es), Polish



Bumper F, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Repair and paint (complete)



Wheel arch cover FR, Scratch(es), Replace



Roof, Dent(s), Repair and paint (complete)



<b>Kenteken</b>	L188JG
<b>Merk Model</b>	Volkswagen ID 4 Outgoing 150kW / 77kWh 1ST Automaat
<b>Brandstofsoort</b>	Elektrisch
<b>Datum deel1</b>	28-06-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
22-04-26	107.407	Reparatie band(en)
02-07-25	85.100	Vervanging band
25-06-25	84.555	Reparatie band(en)
03-06-25	83.946	APK
14-10-24	72.150	Tankklepmotor
24-04-24	64.477	Reparatie band(en)
24-04-24	64.477	Ruitenwischerblad(en) achterzijde
24-04-24	64.477	Ruitenwischerblad(en) voorzijde
28-06-23	45.679	High Voltage lader aansluiting
28-06-23	45.679	Onderhoudsbeurt
28-06-23	45.679	Remvloeistof
28-06-23	45.679	Uitlijnen voor en achterwielen
28-06-23	45.679	Vervanging band
28-12-21	10.355	High Voltage batterij