



Tesla Model Y: 2

Vinnumber:	LRWYGCEK1NC256385	Versionname:	
First Registrationdate:	14/03/2022	Fiscalpower:	
Expertise Mileage:	117821	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3532
Fueltype:	Electric		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Panoramic roof	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	Tow bar removable
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

	255/45/19/92 H			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				255/45 R 19 92 H
Tyre size FR				255/45 R 19 92 H
Tyre size RL				255/45 R 19 92 H
Tyre size RR				255/45 R 19 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Total cost ex VAT	532,12
Bonnet, Scratch(es), Acceptable	0,00



Wing RL, Chemical polution, Acceptable	0,00
--	------



Alloy rim RL, Scratch(es), Repair and paint (complete)	133,03
--	--------



Alloy rim FL, Scratch(es), Repair and paint (complete)	133,03
--	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Bumper trim R, Scratch(es), Acceptable	0,00
--	------



Alloy rim FR, Scratch(es), Repair and paint (complete)	133,03
--	--------



Alloy rim RR, Scratch(es), Repair and paint (complete)	133,03
--	--------



Wing RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Wing trim RR, Chemical polution, Acceptable	0,00
---	------

