MACADAM








Peugeot 2008 (UKL): 2CMA172

Vinnumber:	**VR3UDYHSKNJ720679**	Versionname:	**2008 Active Pack 1.5 BlueHDi S&S 110pk/cv 5p**
First Registrationdate:	**12/09/2022**	Fiscalpower:	
Expertise Mileage:	**100297**	Power Kw:	**81**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Diesel**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Maintenance book present**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**215/65/16/98 H**			
	Fr.L.	**Vredestein: 6 mm**	Fr.R.	**Vredestein: 6 mm**
	Re.L.	**Continental: 6 mm**	Re.R.	**Continental: 6 mm**

Tyre profile depth FL	**6.0**
Tyre profile depth FR	**6.0**
Tyre profile depth RL	**6.0**
Tyre profile depth RR	**6.0**
Tyre size FL	**215/65 R 16 98 H**
Tyre size FR	**215/65 R 16 98 H**
Tyre size RL	**215/65 R 16 98 H**
Tyre size RR	**215/65 R 16 98 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**2480**
Tyre make FR	**2480**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Emergency spare wheel	**Yes**	Jack	**Yes**

Floor covering FL, Worn, Acceptable




Floor covering FL, Burned, Smart repair




Backrest cover FL, Burned, Replace




Bumper F, Scratch(es), Acceptable




Bumper moulding F, Scratch(es), Acceptable




Door RL, Scratch(es), Acceptable




Wing trim RL, Scratch(es), Replace




Tailgate / Boot, Dent(s), Acceptable




Bumper R, Scratch(es), Acceptable




Door RR, Scratch(es), Acceptable




Alloy rim RR, Scratch(es), Acceptable




Alloy rim FR, Scratch(es), Acceptable




Bodywork, Not original part, Remove lettering




2 CMA 172

Onderhoudshistorie van: VR3UDYHSKNJ720679

ALPHABET

Kenteken	2CMA172
Merk Model	Peugeot 2008 Active Pack 1.5 BlueHDi S&S 110pk/cv 5p
Brandstofsoort	Diesel
Datum deel1	9/12/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
2/26/26	88,682	90000 km	Uitvoeren
2/26/26	88,682	brandstof hoofdfilter	Vervangen
2/26/26	88,682	klein materiaal	
2/26/26	88,682	luchtfilter	Vervangen
2/26/26	88,682	luchtfilter interieur	Vervangen
2/26/26	88,682	oliezeef	Vervangen
2/26/26	88,682	remvloeistof	Vervangen
11/19/25	80,872	halogeenlamp	Vervangen
10/1/25	77,145	pechverhelping buitenland	Uitvoeren
6/15/25	70,007	70000 km	Uitvoeren
6/15/25	70,007	oliezeef	Vervangen
9/9/24	53,699	remschijven en blokken vooraan	Vervangen
6/14/24	49,676	50000 km	Uitvoeren
6/14/24	49,676	brandstof hoofdfilter	Vervangen
6/14/24	49,676	klein materiaal	Uitvoeren
6/14/24	49,676	luchtfilter	Vervangen
6/14/24	49,676	luchtfilter interieur	Vervangen
6/14/24	49,676	oliezeef	Vervangen
6/14/24	49,676	remvloeistof	Vervangen
10/3/23	31,084	30000 km	Uitvoeren
10/3/23	31,084	luchtfilter interieur	Vervangen
10/3/23	31,084	oliezeef	Vervangen