



BMW X1:			
Vinnumber:	WBA31AC0705T90820	Versionname:	
First Registrationdate:	23/06/2021	Fiscalpower:	
Expertise Mileage:	125788	Power Kw:	
Bodytype:		Body colour	Blue
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2214
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options		
Number of keys total	2	Luggage cover
Cruise Control		Front parking sensors
Steering wheel multifunctional		Rear parking sensors
Radio multimedia		Type of Tow bar
Type of headlighting	Headlighting Halogen	No Tow bar
Type of GPS	GPS base	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Type of GPS storage	HD	

Limited Technical Inspection

Tyres

225/55/17/97 W				
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				225/55 R 17 97 W
Tyre size FR				225/55 R 17 97 W
Tyre size RL				225/55 R 17 97 W
Tyre size RR				225/55 R 17 97 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	879,00
Seat cover FL, Tear, Replace	560,77



Bumper F, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Wing RR, Dent(s), Paintless dent repair

95,47



Door FR, Dent(s), Paintless dent repair

95,47



Roof, Dent(s), Paintless dent repair

127,29

