



RENAULT EXPRESS: 7637-MNM

Vinnumber:	VF1RK00371646054	Versionname:	Advance 1.5 Blue dCi 70 kW (95 cv) furgón derivado de turismo 70kW 4P manual
First Registrationdate:	26/02/2024	Fiscalpower:	
Expertise Mileage:	180403	Power Kw:	
Bodytype:	Transporter	Body colour	White
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	2		
Number head rests	2		
Type of rims (mounted)	Steel		
Certificate of Conformity	No		
Category	Light Commercial Vehicle		
Registration Certificate Car (BE)	No		

Options

Number of keys total	2	Radio
Number keys remote	2	
Windows electric F		
Cruise Control		
Steering wheel multifunctional		
Type of climate control	Manual climate control	

Tyres

	185/65/15/88 T			
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				185/65 R 15 88 T
Tyre size FR				185/65 R 15 88 T
Tyre size RL				185/65 R 15 88 T
Tyre size RR				185/65 R 15 88 T
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

MOT certificate, Missing, Repair/replace (lump sum)




Registration document, Missing, Repair/replace (lump sum)



Interior, Dirty, Cleaning



Rear light L, Broken, Replace



Door trim FL, Deformed / Strained, Replace



Outside rear-view mirror housing L, Scratch(es), Paint



Grille frame, Missing, Replace



Bonnet, Dent(s), Paintless dent repair



Outside rear-view mirror housing R, Scratch(es), Paint



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)



Rear panel, Not original part, Acceptable



Bumper R, Scratch(es), Paint



Boot door panel RL, Dent(s), Repair and paint (complete)



Tyres, No damage, Check



Bodywork, Glue residues, Remove lettering



Roof, Dent(s), Repair and paint (complete)

