



**Renault Mégane:**

Vinnumber:	<b>VF1RFB00767362200</b>	Versionname:	
First Registrationdate:	<b>21/04/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>133530</b>	Power Kw:	
Bodytype:		Body colour:	<b>Blue</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>3406</b>
Fueltype:	<b>Hybrid Petrol</b>		
Maintenance:	<b>OK</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>No</b>		

**Options**

Number of keys total:	<b>2</b>	Seats electric F L:	
Cruise Control:		Sun Roof electric:	
Steering wheel multifunctional:		Luggage cover:	
Seats F heated:		Front parking sensors:	
Radio multimedia:		Rear parking sensors:	
Type of headlighting:	<b>Headlighting LED</b>	Type of Tow bar:	<b>Tow bar removable</b>
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining leather</b>		
Type of climate control:	<b>Autom climate control</b>		
Type of GPS storage:	<b>HD</b>		

**Limited Technical Inspection**

**Tyres**

225/40/18/92 Y				
Summer tyres:	Fr.L.	<b>Vredestein: 4 mm</b>	Fr.R.	<b>Vredestein: 4 mm</b>
	Re.L.	<b>Continental: 3 mm</b>	Re.R.	<b>Continental: 4 mm</b>
Tyre profile depth FL				<b>4.0</b>
Tyre profile depth FR				<b>4.0</b>
Tyre profile depth RL				<b>3.0</b>
Tyre profile depth RR				<b>4.0</b>
Tyre size FL				<b>225/40 R 18 92 Y</b>
Tyre size FR				<b>225/40 R 18 92 Y</b>
Tyre size RL				<b>225/40 R 18 92 Y</b>
Tyre size RR				<b>225/40 R 18 92 Y</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>2480</b>
Tyre make FR				<b>2480</b>
Tyre make RL				<b>256</b>
Tyre make RR				<b>256</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>1</b>		
Number of charging cables (rapid charge):	<b>0</b>		

Total cost ex VAT	<b>760,96</b>
Bonnet, Scratch(es), Polish	<b>0,00</b>



Bumper F, Scratch(es), Spot repair 148,33



Alloy rim FL polished, Scratch(es), Repair and paint (complete) 204,21



Door FL, Scratch(es), Acceptable 0,00



Wing RL, Scratch(es), Acceptable 0,00



Alloy rim RL polished, Rust, Acceptable 0,00



Charging cable (fast), Missing, Check 0,00




Bumper R, Scratch(es), Acceptable 0,00



Alloy rim RR polished, Scratch(es), Repair and paint (complete) 204,21



Wing RR, Scratch(es), Acceptable 0,00



Door FR, Dent(s) and scratch(es), Acceptable 0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

204,21



Door RR, Scratch(es), Acceptable

0,00

