DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	VR1JCYHZ0 RY630054	Registration date	19/12/2024	Exterior Color	Unknown
Brand	DS	Licence Plate	EU-FA 8655	Odometer	41 564 km
Model	DS 7 BlueHDi 130 Performance Line Automa				

Inspection Details

Arrival Date	17/08/2026	Inspection ID	7119970	Inspection date	19/08/2026
Assign Date	17/08/2026	Fleet owner	Leasys FINN	Inspection loc.	Leasys AKB Zörbig






















Generic equipment


Removable element

Spare wheel kit	✓
Toolkit	✓
Rear parcel shelf	✓
Floor mat B	✓
Floor mat F	✓

Technical Document

User manual	✓
Warranty booklet	✓
Log books	✓
Spare key	✓
Key	✓
Remote key	✓
Service	✓

Tyres



Hankook 235/50/19 W All seasons 4.0 mm


Hankook 235/50/19 W All seasons 4.0 mm

Hankook 235/50/19 W All seasons 5.0 mm

Hankook 235/50/19 W All seasons 5.0 mm



Winter kit



235/50/19 V Winter 5.0 mm Superia

235/50/19 V Winter 5.0 mm Superia


235/50/19 V Winter 6.0 mm Superia

235/50/19 V Winter 6.0 mm Superia



Exception / Damage

1



Part	Side panel	Repair Time	2.00	Part Cost	-
Position	Back right	Repair Cost	140.00€	Gross Cost	230.00€
Damages	Dented	Paint Time	1.00	Depreciation %	10.00%
Severity	-	Paint cost	90.00€	Depreciation	- 23.00
Repair mode	Repair	Flat Rate	-	**Net Cost**	**207.00€**

2



Part	Door	Repair Time	-	Part Cost	-
Position	Back right	Repair Cost	-	Gross Cost	50.00€
Damages	Scratched	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Polishing	Flat Rate	50.00€	**Net Cost**	**50.00€**

3

Part	Bumper	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Stone impact	Paint Time	-	Depreciation %	10.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

4

Part	Bonnet	Repair Time	-	Part Cost	-
Position	-	Repair Cost	-	Gross Cost	-
Damages	Stone impact	Paint Time	-	Depreciation %	10.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

5

Part	Windscreen	Repair Time	-	Part Cost	-
Position	-	Repair Cost	-	Gross Cost	-
Damages	Stone impact	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

6		Part	Bumper	Repair Time	-	Part Cost	-
		Position	Back	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	10.00%
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	**Net Cost**	-
7		Part	Caisse de chargement complète	Repair Time	-	Part Cost	-
				Repair Cost	-	Gross Cost	-
		Position	-	Paint Time	-	Depreciation %	10.00%
		Damages	Scratched	Paint cost	-	Depreciation	-
		Severity	-	Flat Rate	-	**Net Cost**	-
		Repair mode	For info				

Summary Inspection

Gross Price	280.00€	Depreciation	-23.00€	Net Price	257.00€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	70.00€	2.00	140.00€	10.00 %	-14.00€	126.00€
Paintwork	90.00€	1.00	90.00€	10.00 %	-9.00€	81.00€
Paint preparation	90.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	0.00€	-	-	0.00€
Flat Rate	50.00€	-	-	50.00€