



Audi A4

Vinnumber:	WAUZZZF44MA056600	Versionname:	AUDI A4 AVANT 2.0 35 TDi 120kW S tr Adv Business
First Registrationdate:	3/05/2021	Fiscalpower:	Ed 163PK 5d/p AUT (8WDBJG)
Expertise Mileage:	171658	Power Kw:	120
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1213
Fueltype:	Hybrid Diesel		
Maintenance:	OK		
Maintenance:	over 12400 km		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Sun Roof electric	
Seats F heated		Panoramic roof	
Radio multimedia		Luggage cover	
Type of headlighting	Headlighting LED	Front parking sensors	
Type of GPS	GPS big screen color	Rear parking sensors	
Type of Lining	Lining leather	Type of Tow bar	Tow bar collapsible
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Tyres

	225/50/17/98 V			
Summer tyres:	Fr.L.	Semperit: 4 mm	Fr.R.	Semperit: 3 mm
	Re.L.	Pirelli: 3 mm	Re.R.	Pirelli: 2 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				3.0
Tyre profile depth RL				3.0
Tyre profile depth RR				2.0
Tyre size FL				225/50 R 17 98 V
Tyre size FR				225/50 R 17 98 V
Tyre size RL				225/50 R 17 94 H
Tyre size RR				225/50 R 17 94 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2477
Tyre make FR				2477
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1696,99
-------------------	---------

GPS, Not functioning (well), Acceptable	0,00
---	------



Windscreen, Stone chip(s), Acceptable

0,00



Bonnet, Dent(s) and scratch(es), Repair and paint (complete)

406,19



Bumper F, Scratch(es), Repair and paint (complete)

296,58



Step L, Dent(s) and scratch(es), Acceptable

0,00





Wing RL, Scratch(es), Acceptable

0,00



Door FL, Scratch(es), Acceptable

0,00



Outer sill L, Scratch(es), Acceptable

0,00



Alloy rim FL, Scratch(es), Repair and paint (complete)

133,03



Alloy rim RL, Scratch(es), Repair and paint (complete)

133,03



Boot lid covering R, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Repair and paint (complete)

296,58



Step R, Dent(s) and scratch(es), Acceptable	0,00
---	------



Wing RR, Scratch(es), Repair and paint (complete)	431,58
---	--------



Door FR, Scratch(es), Acceptable	0,00
----------------------------------	------

