



AUDI Q2: GP-012-CD

Vinnumber:	WAUZZZG88PA048606	Versionname:	AUDI Q2 30 TDI 116 S Tronic Business Line VP [5P] bva 7-116CH-6cv (SUV)
First Registrationdate:	24/05/2023	Fiscalpower:	
Expertise Mileage:	29558	Power Kw:	85
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	Lining Other
Type of climate control	Autom climate control		

Tyres

215/55/17/98 W				
Summer tyres:	Fr.L.	Pirelli: 20%	Fr.R.	Pirelli: 25%
	Re.L.	Continental: 30%	Re.R.	Continental: 35%
Tyre profile depth FL				6.8
Tyre profile depth FR				6.5
Tyre profile depth RL				6.1
Tyre profile depth RR				6.0
Tyre size FL				215/55 R 17 98 W
Tyre size FR				215/55 R 17 98 W
Tyre size RL				215/55 R 17 98 W
Tyre size RR				215/55 R 17 98 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)



Interior, Dirty, Cleaning



Alloy rim RR, Scratch(es), Repair/replace (lump sum)



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Wing trim FL, Scratch(es), Paint



Wing trim RL, Scratch(es), Polish



Door FL, Scratch(es), Paint



Bumper moulding FL, Scratch(es), Paint



Bumper F, Scratch(es), Polish



Bumper moulding FR, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Paint



Door FR, Dent(s), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Paint



Bumper moulding R, Deformed / Strained, Replace and paint



Historique Maintenance

Immatriculation: **GP-012-CD**

Date de 1ère immatriculation: **24/05/2023**

Modèle: **Audi Q2 30 TDI 116 S Tronic Business Line VP [5P] bva 7-116CH-6cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
02/06/2025	20.323		RECYCLAGE
	0		REVISION
	0		BALAISS ESUIE GLACE AV
	0		LIQUIDE LAVE GLACE
	0		FILTRE CLIM RPLT
	0		LIQUIDE DE FREIN
29/05/2024	10.392	VGRF GRAND PARIS	LIQUIDE LAVE GLACE
	0		BALAISS ESUIE GLACE AV
	0		BALAI ESUIE GLACE AR
	0		RECYCLAGE
	0		REVISION