



Expertise

Protocol number: 46787665
Order No. / Reference: 26529969
Inspection date: 28 Jul 2026

Manufacturer: Volvo

Model: C40 Recharge Twin Motor Ultimate

VIN: YV1XKERR1R2091122



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volvo C40 Recharge Twin Motor Ultimate	
Vehicle Identification number	YV1XKERR1R2091122
Mileage (Read)	137,577 km
First registration	14 Aug 2023
Number of holders	1
Next periodical technical inspection	08/2026
(Report not on hand)	
Fuel type	Electric
Power	183 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	All-wheel drive
Type of vehicle	Saloon car
Colour / colour code	Onyx Black Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Anthracite-Black
readiness to drive	Not roadworthy / moveable



Vehicle details

Maintenance booklet / proof	Non-existent	Next maintenance in	20,355 km
Key is / should be	2 / 2	FZG documents	Registration and title documents unavailable
		Letter No.	GV801414
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	9101 / BYJ 00001		
Emission standard	2017/1151	fine dust sticker	
Permitted total weight	2,620 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/45 R20 100H	All-season tyres on Light alloy	Michelin	5mm / 5mm
2)	235/45 R20 101Y	All-season tyres on Light alloy	Pirelli	6 mm
	235/45 R20 101Y	Winter tyres on Light alloy	Pirelli	6 mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/45 R19 104H	Winter tyres on Light alloy	Pirelli	4mm / 4mm
2)	255/45 R19 104H	Winter tyres on Light alloy	Pirelli	4mm / 4mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Equipment

- Klimaautomatik

|



Standard equipment

- Integrated, removable waste bin in the center console
- Passenger side airbag can be deactivated
- Alarm system with motion/tilt sensor and security lock
- Android infotainment system
- Fold-out (bag) hook on the glove compartment
- Electrically folding exterior mirrors
- Heated exterior mirrors and rear window
- Hill Start Assist (HSA)
- On-board computer
- Colored glazing
- Anthracite headliner
- Deactivating the high-voltage battery
- Digital Instrumentation 2nd Gen.
- Driver Assistance
- Pass-through hatch behind the center armrest in the rear
- Aluminum door sill plates with Recharge lettering, front
- Electronic Stability Control (ESC)
- Advanced air purification system
- Electric windows front and rear
- Automatic emergency braking
- Front luggage compartment (31 liters)
- Transmission: 1-speed direct drive
- Automatic tailgate
- Interior and exterior mirrors automatically dimming
- ISOFIX mounts
- Child safety lock for the rear doors (electric)
- Headrests of the 2nd row of seats can be folded down (electrically)
- Stainless steel loading sill protector in the luggage compartment
- LED taillights with welcome sequence
- Steering wheel adjustable for height and reach
- Steering wheel: Multifunction buttons on the steering wheel
- Illuminated makeup mirror for driver and front passenger
- Front center armrest with integrated storage compartment
- One Pedal Drive
- Panoramic glass roof, fixed
- Electric parking brake
- Parking ticket holder
- Radio accessories: Two USB-C ports in the center tunnel (front and rear)
- Recharge Twin emblem on the rear of the vehicle
- Tire pressure monitoring system
- Run-off Road Protection
- Rear seats can be folded down in a 60/40 split or completely.
- Whiplash Protection System (WHIPS)
- Service, maintenance and wear
- Seat belts
- Seats: Passenger seat adjustable in height and length
- Seats: Driver's seat electrically adjustable
- Seats: Driver's seat height and length adjustable including tilt adjustment
- Acoustic Vehicle Alerting System (AVAS)
- Airbags
- All-wheel drive (AWD)
- Anti-lock braking system (ABS) with electronic brake force distribution
- Electrically adjustable exterior mirrors
- Hill Descent Control (HDC)
- LED turn signals integrated into the exterior mirrors
- third brake light
- Convenient Entry and Start
- Roof edge spoiler
- Digital services including Google Maps navigation system
- Tachometer
- Driver Awareness
- Front and rear parking sensors with automatic braking intervention (rear)
- Electronic differential lock
- Foldable cargo floor with fastening system for carrier bags in the luggage compartment
- Guarantee
- Luggage compartment partition net
- Cup holders (2) in front, integrated into the center console
- Rear spoiler
- Interior lighting
- Keyless Drive
- Automatic climate control with 2-zone temperature control
- Front headrests
- Charging cable Type 2 / Type 2 (Mode 3)
- Charging indicator
- LED fog lights
- LED headlights "Thor's Hammer"
- Steering wheel: Steering wheel heating
- Steering wheel: Sports steering wheel
- Rear center armrest with two integrated cup holders
- Emergency brake lights
- Optical underride protection front and rear in high-gloss black
- Parking camera with 360° surround view
- Radio: Premium Sound audio system by Harman Kardon
- Recharge Pure Electric front grille and grille surround in body color
- Rain sensor
- Roadside Assistance
- Wheels: Tire sealant
- Safety Assistance
- Headlight cleaning system
- Side window trim in high-gloss black (bottom)
- Speed-sensitive power steering
- Seats: Passenger seat electrically adjustable
- Seats: Adjustable (manual) leg rest for driver and front passenger seats



- Seats: Heated front seats
- Sport exterior mirrors in high-gloss black
- Phone: Inductive smartphone charging system (Qi standard)
- First aid kit and warning triangle
- Volvo On Call
- heat pump

- Seats: Lumbar support (4-way electrically adjustable) for driver and front passenger seats
- Sport front and rear apron
- Electric auxiliary heater with timer
- Textile floor mats front and rear
- Trailer Stability Assist (TSA)
- Lashing eyes (four) in the luggage compartment
- Immobiliser
- Central locking system with two remote controls and integrated emergency keys

Extra equipment

- Towbar (semi-electric)
- Upholstery: Connect Textile/Microtech (imitation leather) (incl. rear center armrest - Backlit inlay: Topography - Headliner: Anthracite)
- Glazing: Side and rear windows tinted (from the B-pillar back)
- Paint finish: Metallic paint
- Wheels: 20" 5-spoke sport design alloy wheels (diamond cut/high-gloss black with Recharge all-season tires 235/45 R20 (front) and 255/40 R20 (rear) 8.0 x 20" (front), 9.0 x 20" (rear))

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 1 (registration document) and the vehicle registration certificate Part 2 (title) were not available.
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratched - Smart repair
2	Front axle	Axles / undercarriage (wegen der beschädigten Felgen) - Specify findings - Measure
3	Door - rear right side	Door - Scratched - Smart repair
4	Wheel / tyres	Tyre - rear right side (nicht fahrbereit) - Broken / torn - Replace
5	Wheel / tyres	Tyre - front right side (nicht fahrbereit) - Broken / torn - Replace
6	Wheel / tyres	Tyre - front left side (nicht fahrbereit) - Broken / torn - Replace
7	Boot lid / rear door	Rear spoiler - Stone chips - Paint
8	Front bumper	Front bumper - Scratch(es) - Paint
9	Wheel / tyres	Alloy rim - rear right side (Materialabtrag) - Scratched - Replace
10	Wheel / tyres	Alloy rim - front left side (Materialabtrag) - Scratched - Replace
11	Wheel / tyres	Alloy rim - front right side (Materialabtrag) - Scratched - Replace
12	Vehicle glazing	Windscreen (kein Staubschutz) - Stone chips - Replace



Wear and tear

No.	Component group	Description
1	Door - front right side	Door - Abrasion - No deduction
2	Rear bumper	Rear bumper - Scratch(es) - No deduction
3	Boot lid / rear door	Boot lid - Stone chips - No deduction
4	Misc.	Main inspection - No evidence - No deduction
5	Door - front left side	Door edge - Scratch(es) - Cover / polish
6	2nd wheel set	1 alloy rim (gehört nicht zur Ausstattung) - Scratched - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Der beiliegende Radsatz ist nicht Bestandteil der vorliegenden Fahrzeugausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Additional tyres



Figure 17: Additional tyres



Figure 18: Additional tyres




Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.





Figure 33: Misc.




Figure 34: Misc.



Damage 1: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 1: Rear bumper: Rear bumper - Scratched - Smart repair




Damage 1: Rear bumper: Rear bumper - Scratched - Smart repair




Damage 1: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 3: Door - rear right side: Door - Scratched - Smart repair



Damage 3: Door - rear right side: Door - Scratched - Smart repair



Damage 4: Wheel / tyres: Tyre - rear right side (nicht fahrbereit) - Broken / torn - Replace



Damage 4: Wheel / tyres: Tyre - rear right side (nicht fahrbereit) - Broken / torn - Replace



Damage 5: Wheel / tyres: Tyre - front right side (nicht fahrbereit) - Broken / torn - Replace



Damage 5: Wheel / tyres: Tyre - front right side (nicht fahrbereit) - Broken / torn - Replace



Damage 6: Wheel / tyres: Tyre - front left side (nicht fahrbereit) - Broken / torn - Replace



Damage 6: Wheel / tyres: Tyre - front left side (nicht fahrbereit) - Broken / torn - Replace



Damage 7: Boot lid / rear door: Rear spoiler - Stone chips - Paint



Damage 7: Boot lid / rear door: Rear spoiler - Stone chips - Paint



Damage 7: Boot lid / rear door: Rear spoiler - Stone chips - Paint



Damage 7: Boot lid / rear door: Rear spoiler - Stone chips - Paint



Damage 8: Front bumper: Front bumper - Scratch(es) - Paint



Damage 8: Front bumper: Front bumper - Scratch(es) - Paint



Damage 8: Front bumper: Front bumper - Scratch(es) - Paint



Damage 9: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Scratched - Replace



Damage 9: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Scratched - Replace




Damage 9: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Scratched - Replace



Damage 9: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Scratched - Replace



Damage 10: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace



Damage 10: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace



Damage 11: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratched - Replace



Damage 11: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratched - Replace



Damage 11: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratched - Replace



Damage 12: Vehicle glazing: Windscreen (kein Staubschutz) - Stone chips - Replace



Damage 12: Vehicle glazing: Windscreen (kein Staubschutz) - Stone chips - Replace



Damage 12: Vehicle glazing: Windscreen (kein Staubschutz) - Stone chips - Replace



Damage 12: Vehicle glazing: Windscreen (kein Staubschutz) - Stone chips - Replace



Damage 12: Vehicle glazing: Windscreen (kein Staubschutz) - Stone chips - Replace



Damage 12: Vehicle glazing: Windscreen (kein Staubschutz) - Stone chips - Replace



Wear and tear 5: Door - front left side: Door edge - Scratch(es) - Cover / polish



Wear and tear 5: Door - front left side: Door edge - Scratch(es) - Cover / polish



Wear and tear 5: Door - front left side: Door edge - Scratch(es) - Cover / polish



Wear and tear 6: 2nd wheel set: 1 alloy rim (gehört nicht zur Ausstattung) - Scratched - No deduction



Wear and tear 6: 2nd wheel set: 1 alloy rim (gehört nicht zur Ausstattung) - Scratched - No deduction



Wear and tear 6: 2nd wheel set: 1 alloy rim (gehört nicht zur Ausstattung) - Scratched - No deduction



Wear and tear 6: 2nd wheel set: 1 alloy rim (gehört nicht zur Ausstattung) - Scratched - No deduction