SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Rutger Koogh

2-FKC-117

2-FKC-117 · COMBI L2H12.0dCi 150 DCT N-CONNECTA · 13 October 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FKC-117
Manufacturer	NISSAN
Model	Primastar
Model Versions	COMBI L2H12.0dCi 150 DCT N-CONNECTA
Body Type	VAN
Color	Black
Paint Type	Metallic
Production Year	2024
KW	110

Fuel Type	Diesel
VIN	VNVJ4000873222264
Cylinder Capacity	1.997 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	28-05-2024
Odometer	100.314 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	9

Images

























P
R
N
D
L
M
+
-






Accessories

ABS	Fog lights
Airbags	Leather steering wheel
Audio System	Manual air conditioning
Bluetooth car kit	Navigation system
Central door locking	Rear parking sensors
Centre armrest	Rear view camera
Cruise control	Roller cover / parcel shelf
Electric windows front	Steering wheel multifunction
Electrically adjustable exterior mirrors	Tow bar

Condition

Condition exterior	Adequate	Last Maintenance	Unknown
Condition interior	Adequate	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	6 mm	Superia	215 mm	65 mm	16 inch	All Season
Rear Left	9 mm	Superia	215 mm	65 mm	16 inch	All Season
Front Right	6 mm	Superia	215 mm	65 mm	16 inch	All Season
Rear Right	9 mm	Superia	215 mm	65 mm	16 inch	All Season
Spare Tire Type	Fully Fledged					
Spare Tire Profile	8 mm					

Damages




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Fender – Rear Left	Scratch(es)	Stootlijst	Replace	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Reardoor – Left	Scratch(es)	Stootlijst	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Dent(s) & Scratch(es)	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	small dents / small scratches	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Door-edge chipped	Touch-up	No




Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes




Damage Part	Damage Type	Repair Type	Acceptable
spoiler FB	Scratch(es)	Plastic Repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Spray	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Mirror - Rightside	Scratch(es)	Glaasje knipperlicht	Replace	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Mirror - Rightside	Scratch(es)	Behuizing	Replace	No





Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	small dents / small scratches	B stijl	Panelbeating & Spray	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Fender – Rear Right	Scratch(es)	Stootlijst	Replace	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Reardoor – Right	Scratch(es)	Stootlijst	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Skirt – Right	Dent(s) & Scratch(es)	Panelbeating & Spray	No






Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Right	small dents / small scratches	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Small scratch(es)	Replace	No

Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No




Damage Part	Damage Type	Repair Type	Acceptable
Skirt – Right	Scratch(es)	Spray	No






Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Missing	Wieldoppen 4 x	Replace	No