

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia											
				Policyholder				Opposite party				Opposite party company									
				Operation 2026		Claim number			Code / Agency				Date accident 03/07/2026								
				Expert code		Adjuster code			Policy number				Injured person can recover the VAT NOT ESTABLISHED								
Date assignment 03/07/2026		Date first survey 10/07/2026		Place Ascoli Piceno		C/O VAR		Repairs TO START		Photo		Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia Spa - Via Renato Lunelli 27 Trento (TN)												Formerly plate									
Lessee / Co-owner												Date of overhaul									
Vehicle (Brand - Model - Version) FIAT PANDA 0.9 TwinAir Turbo 85cv 4x4 Cross								Plate GE235CL		Vin Chassis ZFABF6G83M3F39698				First Registration 27/01/2021							
Usage status NON CONOSCIUTO		Km 136243		Tyres % 60		Color GRIGIO		Type of enamel METALLIZED/DOUBLE				Consistency of damage		Type of Expert's report NOT DEFINITIVE							
Equipment																					
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0										Wheelbase		Seats No. 0		Axles 0	
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses															
Damaged items / restoration operations								SR		LA		VE		ME		D.M. S.C.		Costs of spare parts			
								Dif Time		Dif Time		Dif Time		Time		+		(VAT excluded)			
1		51978761		Upper side rear bumper trim				L		S		S		S							
1		735598189		Rear wheel arch trim				L		S		S		S							
1		Codice Ricambio		Ripr. targa ant.				L													
1		Codice Ricambio		Griglia inf. paraurti ant.				L													
1		Codice Ricambio		Paraurti post. inf.				L													
1		Codice Ricambio		Ossatura vano porta ant.				R		L											
1		Codice Ricambio		Coppa ruota ant. - PRM				R													
1		Codice Ricambio		Coppa ruota post. - PRM				R													
1		Codice Ricambio		Porta post. - PRM				R													
1		Codice Ricambio		Leva freno di stazion. - PRM																	
1		Codice Ricambio		Volante - PRM																	

New for old value (N)	Remarks Pneum. Barum. 175/65 R15. Spia avaria generica attiva.
-----------------------	--

ALPHABET

Telaio ZFABF6G83M3F39698

GE235CL

FIAT PANDA 0.9 TwinAir Turbo 85cv 4x4 Cross berlina 2v 85CV 5P manuale

Current Odo (Time of Ma	Maintenance Request	Service Type Descriptio	Maintenance Job Description
10.972	13/09/21	Maintenance	Livelli
10.972	13/09/21	Maintenance	Olio Motore
22.800	05/04/22	Tagliando a 20 000 km	Tagliando a 20 000 km
31.911	23/11/22	Maintenance	Olio Motore
70.040	19/09/24	Tagliando a 70 000 km	***Service at 70 000 km
78.253	18/02/25	Maintenance	Revisione Periodica MTC
78.253	18/02/25	Maintenance	Revisione Periodica MTCMO
86.970	11/04/25	Maintenance	Generico