MACADAM







BMW 1 Reeks (UKL): 2BPA636

Vinnumber:	**WBA7K110007K55037**	Versionname:	**116i (F40) 1.5i 109pk/cv 5p Aut.**
First Registrationdate:	**1/02/2022**	Fiscalpower:	
Expertise Mileage:	**80203**	Power Kw:	**80**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**dans 2000 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Winter tyres:	**205/55/16/91 T**			
	Fr.L.	**Goodyear: 6 mm**	Fr.R.	**Goodyear: 6 mm**
	Re.L.	**Goodyear: 7 mm**	Re.R.	**Goodyear: 7 mm**

Tyre profile depth FL	**6.0**
Tyre profile depth FR	**6.0**
Tyre profile depth RL	**7.0**
Tyre profile depth RR	**7.0**
Tyre size FL	**205/55 R 16 91 T**
Tyre size FR	**205/55 R 16 91 T**
Tyre size RL	**205/55 R 16 91 T**
Tyre size RR	**205/55 R 16 91 T**
Tyre type FL	**Winter**
Tyre type FR	**Winter**
Tyre type RL	**Winter**
Tyre type RR	**Winter**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Seat cover FL, Stain, Cleaning




Bonnet, Scratch(es), Repair and paint (complete)




Bumper F, Scratch(es), Repair and paint (complete)




Door RL, Dent(s) and scratch(es), Acceptable




Alloy rim FL, Scratch(es), Repair and paint (complete)




Alloy rim RL, Scratch(es), Repair and paint (complete)




Luggage compartment cover, Broken, Replace






Alloy rim FR, Scratch(es), Repair and paint (complete)





Bodywork, Paint measurement, Acceptable



Onderhoudshistorie van: WBA7K110007K55037

ALPHABET

Kenteken	2BPA636
Merk Model	BMW 116i (F40) 1.5i 109pk/cv 5p Aut.
Brandstofsoort	Benzine
Datum deel1	2/1/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
10/23/25	64,733	batterij	Vervangen
10/23/25	64,733	BMW/MINI service standaard omvang	Uitvoeren
10/23/25	64,733	BMW/MINI service voertuig-check	Uitvoeren
10/23/25	64,733	bougie	Vervangen
10/23/25	64,733	klein materiaal	
10/23/25	64,733	koelwatervloeistof	Bijvullen/-laden
10/23/25	64,733	remvloeistof	Vervangen
10/23/25	64,733	ruitenwisserrubber achter	Vervangen
10/23/25	64,733	service luchtfilter	Uitvoeren
10/23/25	64,733	service microfilter	Uitvoeren
10/23/25	64,733	service motorolie	Uitvoeren
5/15/24	37,942	BMW/MINI service standaard omvang	Uitvoeren
5/15/24	37,942	klein materiaal	Uitvoeren
5/15/24	37,942	remblokken achter	Vervangen
5/15/24	37,942	remblokken vooraan	Vervangen
11/9/23	30,869	BMW/MINI service standaard omvang	Uitvoeren
11/9/23	30,869	klein materiaal	Uitvoeren
11/9/23	30,869	service microfilter	Uitvoeren
11/9/23	30,869	service motorolie	Uitvoeren