



VOLKSWAGEN GOLF VII:

Vinnnumber:	WVWZZZAUZJW263212	Versionname:	1.0 TSi 81kW Comfortline
First Registrationdate:	1/06/2018	Fiscalpower:	
Expertise Mileage:	162200	Power Kw:	81
Bodytype:		Body colour:	Green
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3506
Fueltype:	Petrol		
Maintenance:	OK		
Maintenance:	21500.0		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Sun Roof electric	
Cruise Control:		Luggage cover	
Steering wheel multifunctional:		Front parking sensors	
Radio multimedia:		Rear parking sensors	
Type of headlighting:	Headlighting Halogen	Type of Tow bar:	No Tow bar
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		
Type of GPS storage:	SD present		

Limited Technical Inspection

Tyres

205/55/16/91 H				
Winter tyres:	Fr.L.	Pirelli: 2 mm	Fr.R.	Pirelli: 2 mm
	Re.L.	Other: 4 mm	Re.R.	Other: 3 mm
Tyre profile depth FL				2.0
Tyre profile depth FR				2.0
Tyre profile depth RL				4.0
Tyre profile depth RR				3.0
Tyre size FL				205/55 R 16 91 H
Tyre size FR				205/55 R 16 91 H
Tyre size RL				205/55 R 16 91 H
Tyre size RR				205/55 R 16 91 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				264
Tyre make FR				264
Tyre make RL				263
Tyre make RR				263

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	2829,35
Headrest RM, Missing, Replace	248,94



Headrest RR, Missing, Replace

259,24



Bonnet, Chemical polution, Acceptable

0,00



Alloy rim FL polished, Rust, Acceptable

0,00



Wing FL, Dent(s) and scratch(es), Acceptable

0,00



Door FL, Scratch(es), Acceptable

0,00



A-pillar left, Scratch(es), Acceptable

0,00



Wing RL, Dent(s), Paintless dent repair

95,47



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)

610,11



Wing RL, Scratch(es), Acceptable

0,00



Alloy rim RL polished, Scratch(es), Repair and paint (complete) 204,21



Outside rear-view mirror housing L, Broken, Replace and paint 251,50



Mirror side repeater L, Broken, Replace 87,21



Bumper R, Scratch(es), Acceptable 0,00



Rear light L, Broken, Replace 302,94



Rear spoiler, Scratch(es), Acceptable 0,00




Tailgate / Boot, Dent(s), Acceptable 0,00



Rear window, Scratch(es), Replace 0,00



Alloy rim RR polished, Rust, Acceptable 0,00



Wing RR, Scratch(es), Acceptable 0,00



Wing RR, Dent(s), Paintless dent repair 95,47



Door RR, Scratch(es), Acceptable 0,00



Door FR, Dent(s), Acceptable 0,00




Alloy rim FR polished, Scratch(es), Acceptable 0,00



A-pillar right, Scratch(es), Acceptable 0,00



Roof, Chemical polution, Repair and paint (complete) 674,26



Bodywork, Not original part, Remove lettering 0,00

