MACADAM








KIA Sorento: 9979-LXF

Vinnumber:	**KNARM81HDN5088819**	Versionname:	**1.6 T-GDi PHEV Emotion 4x4 7pl P.Luxury todoterreno 195kW 5P automática**
First Registrationdate:	**7/04/2022**	Fiscalpower:	
Expertise Mileage:	**123383**	Power Kw:	
Bodytype:	**SUV**	Body colour	**White**
Gearbox:	**Automatic**	Type of rims (mounted)	**Aluminium**
Transmission:			
Fueltype:	**Plug-in hybrid**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**7**		
Number head rests	**7**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**No**		

Options

Number of keys total	**2**	Seats electric F L	
Number keys remote	**2**	Seats electric F R	
GPS big screen color		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Roof bar alu	
Steering wheel leather			
Seats F heated			
Radio multimedia			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**235/55/19/105 Y**			
	Fr.L.	**Goodyear: 5 mm**	Fr.R.	**Goodyear: 5 mm**
	Re.L.	**Goodyear: 5 mm**	Re.R.	**Goodyear: 5 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**235/55 R 19 105 Y**
Tyre size FR	**235/55 R 19 105 Y**
Tyre size RL	**235/55 R 19 105 Y**
Tyre size RR	**235/55 R 19 105 Y**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**
Number of charging cables (rapid charge)	**1**		

Registration document, Missing, Repair/replace (lump sum)




Outside rear-view mirror base L, Scratch(es), Paint




Bumper F, Scratch(es), Repair and paint (complete)





Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)




Windscreen, Stone chip(s), Replace




Door FR, Dent(s) and scratch(es), Repair and paint (complete)




Door RR, Scratch(es), Repair and paint (complete)




Spoiler R, Scratch(es), Paint




Reflector, Broken, Replace




Tyres, No damage, Check











ALPHABET

Datos del vehículo

Marca	KIA	Matrícula	9979-LXF
Modelo	Sorento	VIN	KNARM81HDN5088819
Versión	1.6 T-GDi PHEV Emotion 4x4 7pl P.Luxury todoterreno 195kW 5P automática		

Histórico

Fecha	Descripción	Kilómetros	Taller
09/02/2023	Faros derecho delantero	0	AUTOS SELIKAR S.L
06/05/2022	Paragolpes delantero, Capó, Faros delant dcho	2320	Talleres Montejo y Jimenez S.L
01/07/2022	Paragolpes delantero, Capó, Faros delant dcho	2320	Talleres Montejo y Jimenez S.L
07/03/2023	Paragolpes delantero	18210	Talleres Los Castillos S.l.
13/03/2023	Paragolpes trasero | Paragolpes delantero	18593	Talleres Los Castillos S.l.
12/09/2023	Revisión 2 años	35705	SHUMA GAMBOA S.L.
29/02/2024	Sustitución | Armeros, Rev. 50.000 kms	50659	NEUMATICOS SOLEDAD S.L.
20/09/2024	Rev. 60.000 kms	65229	SHUMA GAMBOA S.L.
19/05/2025	Aceite motor - Precio litro pactado, Arandela / tapón cárter, Bujía, Filtro aceite, Serv inspección 75000 KM, Serv inspección 75000 KM - Nueva, Tasa de gestión de aceites usados	80717	SHUMA GAMBOA S.L. (MAJADAHONDA)
21/11/2025	Aceite motor - Precio litro pactado, Arandela / tapón cárter, Filtro aceite, Filtro antipolen, Líquido frenos - DOT4 SAE - Nueva, Líquido lavaparabrisas, Serv inspección 90000 KM, Sustituir Líquido lavaparabrisas, Tasa de gestión de aceites usados	96628	SHUMA GAMBOA S.L. (MAJADAHONDA)
21/04/2025	Puerta trasera derecha, Paragolpes delantero	99000	TALLERES JOS & CAR S.L.U.
03/03/2026	Alineado doble, Ecotasa - N2, Goodyear / 588740 - 235/55R19 105Y EAG F1 ASY 6 XL,	107418	SERVICIOS AUXILIARES DE AUTOMOCION RODEX S.A.

Fecha	Descripción	Kilómetros	Taller
	Sustitucion y kit de montaje		
01/04/2026	Aceite motor - - - ALP 5, Arandela / tapón cárter, Correa accesorios, Escobilla dr limpiaparabrisas, Escobilla iz limpiaparabrisas, Escobilla limpialuna tr, Filtro aceite, Líquido lavaparabrisas, Serv inspección 105000 KM, Sustituir Escobilla limpialuna tr, Sustituir Escobillas limpiaparabrisas, Sustituir Líquido lavaparabrisas, Tasa de gestión de aceites usados	112066	SHUMA GAMBOA S.L. (MAJADAHONDA)