



Expertise

Protocol number: 46668126
Order No. / Reference: 26664721
Inspection date: 23 Jul 2026

Manufacturer: Skoda
VIN: TMBLE7NU3R5055870

Model: Karoq 2.0 TSI 4x4 DSG Sportline



Vehicle details	
Manufacturer / Type / Model / Equipment	
Skoda Karoq 2.0 TSI 4x4 DSG Sportline	
Vehicle Identification number	TMBLE7NU3R5055870
Mileage (Read)	36,641 km
First registration	11 Oct 2024
Number of holders	1
Next periodical technical inspection	10/2027
(Report not on hand)	
Fuel type	Petrol
Engine displacement / Cylinder	1,984 ccm / 4
Power	140 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	Graphite Grau Metallic (F7C)
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	22,200 km
Last service on / at	11/2025 at 28,778 km		
Key is / should be	3 / 3	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HG806377
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8004 / ATK 01070		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,160 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/50 R18 95W	Summer tyres on Light alloy	Goodyear	6mm / 6mm
2)	225/50 R18 95W	Summer tyres on Light alloy	Goodyear	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98V	Winter tyres on Light alloy	Pirelli	7mm / 7mm
2)	215/55 R17 98V	Winter tyres on Light alloy	Pirelli	8mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 07/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Airbag, driver's knee airbag
- Airbag, front side airbags
- Permanent all-wheel drive
- Traction control (ASR)
- Electrically folding exterior mirrors including interior and driver's side mirrors with automatic dimming
- Exterior mirrors in black, door handles painted in body color
- Hydraulic brake assist (HBA)
- Third vehicle key
- eCall (automatic emergency call function in case of an accident with airbag deployment)
- ESC Electronic Stability Control
- Electric windows front and rear
- Cruise control
- Transmission: 7-speed dual-clutch transmission (DSG)
- Illuminated glove compartment
- Heated rear window
- Automatic interior mirror dimming
- Interior Design Sportline (seat covers in black fabric - dashboard and door trim in black - decorative strips in "black" - door trim in "carbon look" - headliner in black)
- Front headrests are fixed, rear headrests are height-adjustable.
- Steering wheel: Heated sports leather steering wheel (DSG) with multifunction buttons
- Front center armrest, including storage compartment
- Engine drag torque control (MSR)
- Fog light
- Package: Light & Sight (Matrix LED headlights - LED ambient lighting and footwell lighting, boarding spot logo projector on the front doors - Dynamic Light Assist)
- Package: Winter PLUS (Heated front and outer rear seats - Headlight cleaning system - Heated windshield)
- Tire Mobility Kit
- Tire pressure monitoring
- Rear seat backrest split 60:40, foldable
- Electromechanical power steering
- Karoq seat belts
- Seats: Height-adjustable front seats
- Skoda Care Connect
- Sun visor on driver and passenger side with illuminated vanity mirror
- 12V socket - in the center console
- Telephone: Comfort hands-free telephone system
- Traffic sign recognition
- Preparation for a trailer hitch
- Central locking with remote control
- Airbag, driver and passenger
- Airbag, head airbags
- Allergen filter
- Anti-lock braking system (ABS)
- Attention and fatigue detection
- Electrically adjustable and heated exterior mirrors with integrated side indicators
- Illuminated trunk
- Hill start and descent assist
- Roof rails, black
- Easy Start (start-stop button)
- Electronic parking brake including auto-hold function
- Electronic transverse differential lock (XDS+)
- Driving light assistant and rain sensor
- Front radar assistant including city emergency braking function with pedestrian detection
- Green tec (start/stop system and brake energy recuperation)
- Aero rear window wiper including windshield washer system
- ISOFIX preparation on the outer rear seats
- Kessy (keyless entry and start-stop system)
- Trunk cover, fixed
- LED brake light in the rear spoiler
- LED taillights in crystal glass look
- Reading lights at the front of the headliner
- Rear center armrest with cup holders and pass-through option
- Multi-collision brake
- Otto particulate filter
- Package: Sport (4x4) (Adaptive chassis DCC incl. driving profile selection - progressive steering - stainless steel look pedals - off-road assistant)
- Radio accessories: Digital radio reception DAB+
- Radio accessories: USB port in the center console (Type-C)
- Wheels: 18" alloy wheels Procyon black gloss turned, Aero black matt (4x4) (wheels 7J x 18, ET 45 - tires 225/50 R18 95W)
- Seats: Adjustable lumbar support in the front seats
- Seats: Remote release of the rear seat backrests (2nd row) in the boot
- Speed limiter
- Lane keeping assistant (Lane Assist)
- Bumpers partially painted in body color
- Textile floor mats
- Lashing eyes in the trunk
- Immobiliser



Extra equipment

- Electric tailgate operation with comfort opening
- Paint finish: Metallic
- Package: Driving Assistance Plus (DSG) (Predictive Adaptive Cruise Control pACC (control range up to 210 km/h) - Adaptive Lane Keeping Assist - Traffic Sign Recognition - Capacitive Steering Wheel with Hands Off Detection - USB-C Charging Port on the Interior Mirror - Emergency and Traffic Jam Assist - Lane Change Assist (Blind Spot Detection) and Parking Assist)
- Skoda Infotainment Online (online map updates for navigation - display of weather data, news, headlines - petrol stations and parking space search and much more)
- Climatronic air conditioning (3-zone) (fully automatic, separately adjustable for driver, front passenger and rear seats)
- Package: Infotainment (Dynamic radio navigation system (Amundsen) and 8" color display - Digital Cockpit Plus - Wireless SmartLink - Voice control - Phonebox with inductive charging function - Infotainment Online (3-year term))
- Package: Parking (front and rear parking sensors - reversing camera)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Wear and tear

No.	Component group	Description
1	Trim / covers	C-pillar - trim - interior, right side - Scratch(es) - No deduction
2	Front bumper	Bumper with Parktronic - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Documents - Documentation for retrofitted accessories (Winterräder)

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN




Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: TMBLE7NU3R5055870

Hersteller / Modell: SKODA SKODA Karoq 2.0 TSI 4x4 DSG Sportline

Datum	KM-Stand	Beschreibung
26.11.2025	28.778	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges