



RENAULT CLIO: ET-993-VF

Vinnumber:	VF15RBF0A59971092	Versionname:	RENAULT CLIO Business Energy dCi 75 VP [5P] bvm 5-75CH-4cv (bi-corps)
First Registrationdate:	1/02/2018	Fiscalpower:	
Expertise Mileage:	171244	Power Kw:	55
Bodytype:	Berline	Body colour:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Luggage cover	
GPS big screen color		Rear parking sensors	
Windows electric F		Seat cover lining	Lining Other
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Manual climate control		

Tyres

195/55/16/87 H				
Summer tyres:	Fr.L.	Goodyear: 45%	Fr.R.	Goodyear: 40%
	Re.L.	Hankook: 25%	Re.R.	Hankook: 25%
Tyre profile depth FL				5.4
Tyre profile depth FR				5.7
Tyre profile depth RL				6.5
Tyre profile depth RR				6.5
Tyre size FL				195/55 R 16 87 H
Tyre size FR				195/55 R 16 87 H
Tyre size RL				195/55 R 16 87 H
Tyre size RR				195/55 R 16 87 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Air vent L, Broken, Replace



Interior, Stain, Chemical cleaning



Seat cover FL, Hole, Smart repair



Wheel cover FR, Missing, Replace



Wheel cover RR, Missing, Replace



Wheel cover RL, Missing, Replace



Steel rim RL, Deformed / Strained, Replace



Wheel cover FL, Missing, Replace



Door RL, Dent(s), Repair and paint (complete)



Outer sill L, Dent(s), Repair and paint (complete)



Bumper F, Crack, Replace and paint



Number plate F, Deformed / Strained, Repair/replace (lump sum)



Door FR, Dent(s), Repair and paint (complete)



Side repeater R, Broken, Replace



Outside rear-view mirror base R, Unclamped, Dismount/Mount



Rubber seal for boot lid, Unclasp(ed), Dismount/Mount



Bumper spoiler Rear, Difference in color, Paint



Bumper R, Scratch(es), Repair and paint (complete)



Fuel cap cover, Incomplete, Replace



Historique Maintenance

Immatriculation: **ET-993-VF**

Date de 1ère immatriculation: **01/02/2018**

Modèle: **Renault CLIO Business Energy dCi 75 VP [5P] bvm 5-75CH-4cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
23/04/2026	170.986	GARAGE GUIBERT	DIAG
07/05/2025	152.095	FLEET SOLUTIONS FRANCE	REPLACEMENT PNEUS ETE
24/10/2024	141.500	HAINAUT SERVICES AUTOMOBILES	LIQUIDE DE FREIN
	0		LIQUIDE DE REFROIDISSEMENT RPLT
	0		REVISION
	0		DEPOUSSIERAGE FREINS AR CTRL
	0		BALAI ESSUIE GLACE AR
	0		BALAIS ESSUIE GLACE AV
	0		PLAQUETTES AV RPLT
09/02/2024	121.465	FLEET SOLUTIONS FRANCE	REPLACEMENT PNEUS 4 SAISONS
07/02/2024	121.452	HAINAUT SERVICES AUTOMOBILES	REVISION
	0		AMORTISSEURS AR RPLT
	0		BATTERIE RPLT
	0		FILTRE A AIR RPLT
18/10/2023	111.424	DREUMONT	RECYCLAGE
	0		BALAIS ESSUIE GLACE AV
	0		DISQUES PLAQUETTES AV RPLT
	0		REVISION ET CLIM
21/02/2022	62.376	MILLAUTO LOSANGE MONTBELIARD	REVISION ET CLIM ET AIR ET CARBURANT
	0		PLAQUETTES AV RPLT
04/05/2021	52.838	MILLAUTO LOSANGE MONTBELIARD	SERENITE
	0		LIQUIDE DE FREIN
06/02/2020	29.394	GARAGE MODERNE	REVISION