

## » Overview

**Order number:** 1002203054  
**Order completed:** 08.12.2025 11:24  
**Report number:** 9616129  
**VIN:** TMBJJ8NX1PY064839



Front Left 3/4



Rear Right 3/4



Mileage

## » Vehicle Data

<b>Vehicle category:</b>	Passenger Car
<b>Vehicle type:</b>	EstateCar
<b>Make:</b>	Skoda
<b>Model:</b>	Octavia
<b>Manufacturers and type code:</b>	8004 / AWL
<b>Date of first registration:</b>	15.12.2022
<b>Mileage:</b>	151,739 km
<b>Proof of mileage:</b>	
<b>Exterior colour:</b>	Brilliant-Silber Metallic
<b>Roof colour:</b>	Brilliant-Silber Metallic
<b>Propulsion:</b>	Front
<b>Fuel:</b>	Diesel
<b>Engine size (cc):</b>	2,000 ccm
<b>Performance:</b>	110 kW (150 PS)
<b>Length:</b>	
<b>Height:</b>	
<b>Width:</b>	
<b>Permitted total weight:</b>	
<b>Wheelbase:</b>	
<b>Number of powered axles:</b>	2
<b>Cylinders:</b>	4
<b>Euronorm:</b>	Euro 6
<b>Number of doors:</b>	4
<b>Number of seats:</b>	5
<b>Gearbox:</b>	Automatic 7-speed
<b>Upholstery type:</b>	Lining fabrics
<b>Interior colour:</b>	Schwarz
<b>Number of keys:</b>	2

## » Documents & Maintenance

<b>Statutory inspection date:</b>	
<b>Registration certificate available:</b>	No
<b>Registration certificate received:</b>	No
<b>License plate:</b>	None
<b>Maintenance book:</b>	Digital
<b>Maintenance:</b>	Not testable
<b>Maintenance last date:</b>	
<b>Maintenance last mileage:</b>	

"DRIVER ALERT" - driver alert system	Comfort equipment
"FRONT ASSIST" - with warning and braking reaction to vehicles, pedestrians and cyclists	Comfort telephony with LTE and wireless charging
"SMART LINK" (wired and wireless connect)	Curb weight range 1
"SUNSET" + front side acoustic windows	DAB - Digital radio reception
12-volt socket in luggage boot	Decorative inserts for special edition
230-V inverter and outlet for Europe	Disc brakes in front (Geomet D)
2x USB in front, 2x USB in rear (middle-console), 1x USB in rear-view mirror	Disc brakes in rear
3-point seat belt for center rear seat	Door and side trim panel (umbrella)
3-point seat belts in front, with tensioner and height adjustment	Driver knee airbag
3-point seat belts, outer rear with ECE label	Driving on the right
4 doors	Driving profile selection and conventional shock absorber
4-cyl. turbo diesel 2.0l/110kW(4V) TDI CR; b.eng. T37/T3Y/TS1/T4P/T98/T4S/TR1	Dynamic headlight range control, with cornering light (AFS 1)
T0N/T13/T29/TD1/TI9/T3C/T1N/T27/T1Q/T5M	Electronic differential lock XDS, dynamic traction support
4-cylinder diesel engine 2.0 l unit 05L.C	Electronic immobilizer
7-speed automatic transmission	Emergency call system eCall+
8 speakers (passive)	Emission standard EU6 AP
Adapter	Equipment options subset for Germany
Adaptive cruise control (with "follow-to-stop") and speed limiter	Exterior mirror housings and various add-on parts in body color
Additional el. heating	Exterior mirrors: convex on driver side, convex on front passenger side
Additional exterior noise suppression	Exterior rear view mirrors; glass el. adjusted-auto dimming (driver), heated, housing el. powerf., board.spot(w. KA6)
Additional retro-reflectors (door area)	Floor mats in front and rear
Additional stone guard body covers	Freely programmable instrument cluster Medium
Alloy wheels "PERSEUS", anthracite, bright machining, 7,5J x 18 - 4 pcs	Front fog lamp and cornering lamp
Alloy wheels "PERSEUS", anthracite, bright machining, 7,5J x 18" - 4 pcs	Front head restraints
Alternator 140 A	Front stabilizer bar
AM Tour Comfort package	Front-wheel drive
AM TOUR DE	Fuel system for diesel engine
Antenna for FM reception only, diversity	Heated winscreen washer nozzles
Battery 420 A (70 Ah)	Heat-reflecting windshield
Black decorative trims	Hill start assist
Black roof rails	Initial standard fuel filling (6L)
Brake control system for vehicles without electric drive (ESC and electromechanical brake booster)	Installation differentiation for transmission DQ381 -- vehicle components --
Breakaway interior rearview mirror, auto-dimming	Instrument cluster, km/h speedometer
Breakdown kit	Interior ambient lighting and surround lighting
Center armrest in front	Interior light in footwell in front and rear
Center console	Keyless locking and starting system "Keyless Advanced" without SAFELOCK
Child seat anchors f. child seat system i-Size, 2x top tether and child seat anchors in front on front passenger side	Lane Assist with adaptive lane guidance function + Emergency Assist
Climatronic (3-zone) with air conditioning control panel in rear	Leather-wrapped multi-function steering wheel, heated, with tiptronic
Columbus PLUS Business	LED headlamps with variable light distribution

LED rear combination lamp, variable lighting functions, special styling	Side airbag in front with curtain airbag and interaction airbag in front
Left-hand drive	Special identification label for EC for M1 passenger vehicles
LongLife Service Regime	Special interior noise suppression
Luggage compartment cover, sliding	Special model 2022
Luggage compartment floor covering in needle-punched nonwoven (dimensionally stable)	Speed-related variable steering assist (Servotronic)
Luggage compartment lighting	Standard battery/alternator capacity
Manual child safety lock	Standard bumpers
Manual height adjustment for front seats	Standard climatic zones
Manual in German	Standard dashboard
Manually adjustable lumbar support in front seats	Standard electronic engine sound
Mass damper for steering wheel, XX Hz	Standard manufacturing sequence
Mechanical rear seat release	Standard paint coating
Multiple matrix beam	Standard pedal cluster
Nameplate set in basic style	Standard rear axle
Navi Columbus + Web Radio	Standard seats in front
Net partition	Standard wheel bolts
Net program + cargoelements	Start-stop system with regenerative braking
No special purpose vehicle, standard equipment	Storage compartments in trunk
Not hot country	Sun visors with illuminated vanity mirror on driver and front passenger side
Operating permit, alteration	Suspension range 07 installation control only, no requirement forecast
Optional infotainment system (MIB3)	Tailgate/trunk lid release
Park distance control in front and rear	Three rear head restraints
Parking brake	Tire pressure monitoring system
Part set without country-specific prescriptive standard	Tire suppliers for EU countries
Power windows with comfort operation and circuit breaker	Tires 225/45 R18 91Y
Rear axle weight, type 1	Tool kit
Rear exhaust tailpipe (standard)	Tow bar swiveling, el. unlockable and with adaptor
Rear floor panel module, type 4	Trailer hitch mechanically swiveling and power-detachable
Rear fog light on one side, back-up light on both sides	Transport protection film (minimum protection) with additional transport protection measures
Rear shock absorption, basic version 1	Trims for alloy wheels
Rear spoiler	Two-tone horn
Rear window wiper "AERO"	Type approval country Germany
Refrigerant R1234yf	Unsplit molded headliner
Regional code " ECE " for radio	Unsplit rear seat bench, split folding backrest, with center armrest
Remote Access / Remote Access + Online Infotainment	UWB-capable country and carrier frequency, 433.92 to 434.42 MHz
Remote Access + Infotainment Online 3 years	Vehicle class differentiation -5EN-
Scuff plates in door apertures	Vehicles without special upgrade measures
Seat heater for front and rear seats separately controlled	Vent
Seat trim covers in fabric	Visual and acoustic seat belt reminder, electric contact in front and rear
Separate daytime running light	Voice control
Service indicator 30 000 km or 2 years ( variable )	Wagon/Avant
Shock absorption in front	

Weight range 12 installation control only, no requirement forecast

Wheelbase

Windshield wiper intermittent control with light/rain sensor

With bracket

With dynamic road sign display

With emergency steering support with turn assist

With multifunction camera

Without activated carbon canister with SCR

Without additional front underbody guard

Without additional malfunction display

Without additional tires

Without alternative drive system

Without auxiliary heater/parking heater

Without backrest release for front seats

Without camera systems

Without camera systems/accident sensors

Without Car2X

Without charging cable

Without delivery equipment

Without electric motor (hybrid)

Without extended safety system

Without folding table on front seat backrest

Without follow-on warranty

Without gearshift knob/handle

Without headlamp washer system

Without head-up display

Without lane change assist

Without locking and starting systems

Without luggage/load compartment floor

Without mode 3 charging cable

Without mud flap

Without rear stabilizer bar

Without roof insert (standard roof)

Without seat ventilation/massage seat

Without second battery

Without ski bag

Without special body measures

Without speed limiter

Without storage compartment package/box

Without supertone system and tone sequence control

## » Tyres

### MOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Bridgestone	Front	Left	Winter	Aluminium	205/55 R 17 95 V	7.0 mm
Bridgestone	Front	Right	Winter	Aluminium	205/55 R 17 95 V	7.0 mm
Bridgestone	Rear	Left	Winter	Aluminium	205/55 R 17 95 V	5.0 mm
Bridgestone	Rear	Right	Winter	Aluminium	205/55 R 17 95 V	5.0 mm

**Permitted:** Yes

**Roadworthy:** Yes

### UNMOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Goodyear			Summer	Aluminium	225/45 R 18 91 Y	4.0 mm
Goodyear			Summer	Aluminium	225/45 R 18 91 Y	4.0 mm
Falken			Summer	Aluminium	225/45 R 18 95 W	3.0 mm
Falken			Summer	Aluminium	225/45 R 18 95 W	3.0 mm

**Permitted:** Yes

**Roadworthy:** Yes

### SPARE/EMERGENCY TYRE & ACCESSORIES

**Repair kit present:** Yes

**Repair kit expiration date:** 09.2026

**Compressor present:** Yes

## » Devaluation Factors

Nr	Location	Damage type	Repair type
1	Tailgate / Boot	Scratch(es)	Repair and paint (complete)
2	Preparationtime metal painting	Paint preparation	Execute
3	Bumper RM	Scratch(es)	Spot repair
4	Bumper FL	Scratch(es)	Repair and paint (partial)

## » Usage Damages

Nr	Location	Damage type	Repair type
1	Shutter / cover	Scratch(es)	Acceptable
2	Alloy rim RR polished	Scratch(es)	Acceptable
3	Alloy rim FR polished	Scratch(es)	Acceptable
4	Alloy rim FL	Scratch(es)	Acceptable
5	Roof	Stone chip(s)	Acceptable
6	Outside rear-view mirror housing R	Scratch(es)	Acceptable
7	Boot door lining R	Scratch(es)	Acceptable
8	Boot door lining L	Scratch(es)	Acceptable
9	Door FL	Scratch(es)	Acceptable
10	Windscreen	Stone chip(s)	Acceptable
11	Bonnet	Stone chip(s)	Acceptable
12	Bumper moulding FL	Scratch(es)	Acceptable

## » Commercial devaluation

<b>Known previous damages:</b>	No
<b>Previous damages detectable:</b>	No
<b>Repainting present:</b>	No
<b>Paint thickness measurement performed:</b>	Yes - no abnormalities/deviations

### PAINTHICKNESS MEASUREMENT RESULTS

The measured values were in the usual range.

At least 3 measurements were carried out per component.

## » Notes On The Assessment

**Details of the assignment and the scope of the assessment:**

The order was placed to prepare a condition report on the described vehicle.

The vehicle condition assessment was carried out in accordance with the order on the basis of the standards for vehicle assessments specified by the client. The expert makes the findings in the individual case on the basis of his own expertise and at his own expert discretion.

**Vehicle identification:**

TMBJJ8NX1PY064839

VIN check, no comparison with documents possible

**Vehicle condition:**

Dirty

**Inspection condition:**

Wet

**Lifting platform/lifting equipment used:**

No

**Testdrive carried out:**

Yes

**Engine test carried out:**

Yes

» **Remarks**

This copy was generated electronically. It is valid without an original signature.

## » Commercial Pictures



Front Left 3/4



Front Right 3/4



Rear Left 3/4



Rear Right 3/4



Mileage



Sill outer L



Sill outer R



Chassis nr



Wheel FL



Wheel FR



Wheel RL



Wheel RR



Additional wheel 1



Additional wheel 2



Additional wheel 3



Additional wheel 4



Central console



Engine compartment



Documents



Interior arrangement



Towbar



History Maintenance



Interior - front



Interior - rear



Tirefit expiration date



GPS/Radio

## » Devaluation Damages

### DEVALUATION FACTORS

1 - Tailgate / Boot - Scratch(es) - Repair and paint (complete)



2 - Preparationtime metal painting - Paint preparation - Execute

3 - Bumper RM - Scratch(es) - Spot repair



4 - Bumper FL - Scratch(es) - Repair and paint (partial)



### USAGE DAMAGES

1 - Shutter / cover - Scratch(es) - Acceptable



2 - Alloy rim RR polished - Scratch(es) - Acceptable



3 - Alloy rim FR polished - Scratch(es) - Acceptable



4 - Alloy rim FL - Scratch(es) - Acceptable



5 - Roof - Stone chip(s) - Acceptable



6 - Outside rear-view mirror housing R - Scratch(es) - Acceptable



7 - Boot door lining R - Scratch(es) - Acceptable



8 - Boot door lining L - Scratch(es) - Acceptable



9 - Door FL - Scratch(es) - Acceptable



10 - Windscreen - Stone chip(s) - Acceptable



11 - Bonnet - Stone chip(s) - Acceptable



12 - Bumper moulding FL - Scratch(es) - Acceptable

