


MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia											
				Policyholder				Opposite party				Opposite party company									
				Operation 2026		Claim number				Code / Agency				Date accident 30/06/2026							
				Expert code		Adjuster code		Policy number				Injured person can recover the VAT									
Date assignment 30/06/2026		Date first survey 09/07/2026		Place PARMA		C/O		Repairs		Photo		Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)														Formerly plate							
Lessee / Co-owner														Date of overhaul							
Vehicle (Brand - Model - Version) CUPRA FORMENTOR 2.0 TDI 4Drive DSG								Plate GN647SV		Vin Chassis VSSZZZKMXP045212				First Registration 27/04/2023							
Usage status NON CONOSCIUTO		Km 48400		Tyres % 50		Color NERO		Type of enamel METALLIZED/DOUBLE				Consistency of damage		Type of Expert's report NOT DEFINITIVE							
Equipment																					
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0										Wheelbase		Seats No. 0		Axles 0	
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses															
Damaged items / restoration operations								SR		LA		VE		ME		D.M. S.C.		Costs of spare parts + (VAT excluded)			
								Dif Time		Dif Time		Dif Time		Time							
1		5FF805903A9DG		Front bumper side spoiler				L		S		S		S							
1		5FF805904A9DG		Front bumper side spoiler				R		S		S		S							
1		5FF807217QGRU		Front bumper						M		M		M							
1		5FF807984GRU		Rear side bumper				R		M		M		M							
1		5FF807434G9DG		Rear bumper						M		M		M							
1		5FF853718F9DG		Front wheel arch trim				R		L		L		L							
1		5FF853818B9DG		Rear wheel arch trim				R		L		L		L							
1		Codice Ricambio		Ripristino dischi in lega N°4																	
1		Codice Ricambio		Chiave mancante																	

New for old value (N)	Remarks Pneum. INV. Pirelli 245/45 R18. Vhl sporco.
-----------------------	---

ALPHABET

Telaio VSSZZZKMXP045212

GN647SV

CUPRA FORMENTOR 2.0 TDI 4Drive DSG sports utility vehicle 150CV 5P automatico

Current Odo (Time of Ma	Maintenance Request	Service Type Descriptio	Maintenance Job Description
19.787	18/10/24	Maintenance	Additivo FAP
19.787	18/10/24	Tagliando a 10 000 km	***Service at 10 000 km
42.660	01/04/26	Maintenance	Generico
42.660	01/04/26	Tagliando a 40 000 km	Tagliando a 40 000 km