



### DS 7 CROSSBACK: [redacted]

Vinnumber:	<b>VR1JCYHZRLY031330</b>	Versionname:	<b>1.5 BlueHDi 130 Automatic So Chic</b>
First Registrationdate:	<b>30/07/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>115701</b>	Power Kw:	<b>96</b>
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>3524</b>
Fueltype:	<b>Diesel</b>		
Maintenance:	<b>OK</b>		
Maintenance:	<b>+ 26700 km</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

### Options

Number of keys total:	<b>2</b>	Seats electric F L:	
Cruise Control:		Seats electric F R:	
Steering wheel multifunctional:		Luggage cover:	
Radio multimedia:		Front parking sensors:	
Type of headlighting:	<b>Headlighting LED</b>	Rear parking sensors:	
Type of GPS:	<b>GPS big screen color</b>	Type of Tow bar:	<b>Tow bar collapsible</b>
Type of Lining:	<b>Lining leather</b>		
Type of climate control:	<b>Autom climate control</b>		
Type of GPS storage:	<b>HD</b>		

### Limited Technical Inspection

### Tyres

235/50/19/103 V				
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>
Tyre profile depth FL				<b>4.0</b>
Tyre profile depth FR				<b>4.0</b>
Tyre profile depth RL				<b>4.0</b>
Tyre profile depth RR				<b>4.0</b>
Tyre size FL				<b>235/50 R 19 103 V</b>
Tyre size FR				<b>235/50 R 19 103 V</b>
Tyre size RL				<b>235/50 R 19 103 V</b>
Tyre size RR				<b>235/50 R 19 103 V</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>261</b>
Tyre make FR				<b>261</b>
Tyre make RL				<b>261</b>
Tyre make RR				<b>261</b>

### Assistance equipment

Emergency spare wheel:	<b>Yes</b>	Jack:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

Total cost ex VAT:	<b>408,42</b>
Centre console, Scratch(es), Acceptable:	<b>0,00</b>



Bumper F, Stone chip(s), Acceptable 0,00



Bumper spoiler F, Scratch(es), Acceptable 0,00



Alloy rim RL polished, Scratch(es), Repair and paint (complete) 204,21



Alloy rim FL polished, Scratch(es), Repair and paint (complete) 204,21



Boot lid covering R, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Rear light R, Waterinfiltration, Acceptable 0,00

