MACADAM









PEUGEOT 3008: GL-552-QS

Vinnumber:	**VF3MCYHZUNS177742**	Versionname:	**PEUGEOT 3008 BlueHDi 130 S&S EAT8 Allure Pack VP [5P] bva 8-130CH-7cv (SUV)**
First Registrationdate:	**13/01/2023**	Fiscalpower:	
Expertise Mileage:	**999999**	Power Kw:	**96**
Bodytype:	**SUV**	Body colour	**White**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Grey**
Fueltype:	**Diesel**	Type of rims (mounted)	**Aluminium**
Engine functioning	**No**	Dashboard color	**Black**
Battery functioning	**No**		
Vehicle running	**No**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**1**	Central consol F	
Number keys remote	**1**	Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Seat cover lining	**Lining Other**
Steering wheel leather			**Lining Leather**
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**225/55/18/102 V**				
	Fr.L.	**Goodyear: 40%**	Fr.R.	**Goodyear: 35%**
	Re.L.	**Goodyear: 45%**	Re.R.	**Goodyear: 45%**

Tyre profile depth FL	**5.6**
Tyre profile depth FR	**5.8**
Tyre profile depth RL	**5.1**
Tyre profile depth RR	**5.3**
Tyre size FL	**225/55 R 18 102 V**
Tyre size FR	**225/55 R 18 102 V**
Tyre size RL	**225/55 R 18 102 V**
Tyre size RR	**225/55 R 18 102 V**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Interior, Stain, Cleaning









Remote ignition key, Missing, Repair/replace (lump sum)



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)





Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)





Door RL, Dent(s), Repair and paint (complete)





Wing RL, Dent(s), Acceptable




Door FL, Dent(s), Repair and paint (complete)





Bumper F, Scratch(es), Paint





Bumper spoiler F, Unclasped, Dismount/Mount




Bumper moulding R, Scratch(es), Replace




Bumper R, Broken, Repair and paint (complete)




ALPHABET

Historique Maintenance

Immatriculation: **GL-552-QS** Date de 1ère immatriculation: **13/01/2023**

Modèle: **Peugeot 3008 BlueHDi 130 S&S EAT8 Allure Pack VP [5P] bva 8-130CH-7cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
07/05/2026	148.964	GEMY COTE D'AZUR LA SEYNE SUR MER	CARDAN AVD RPLT
	0		LIQUIDE DE REFROIDISSEMENT RPLT
	0		REVISION
	0		BALAI ESSUIE GLACE AR
	0		BALAIS ESSUIE GLACE AV
	0		PLAQUETTES AV RPLT
19/09/2025	120.701	GEMY COTE D'AZUR	REVISION
	0		REVISION
	0		FILTRE A AIR RPLT
	0		COURROIE ACCESSOIRES RPLT
04/04/2025	107.701	GEMY COTE D'AZUR	DISQUES PLAQUETTES AR RPLT
	0		REVISION
	0		LIQUIDE DE FREIN
	0		FILTRE CLIM RPLT
	0		BALAIS ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
27/08/2024	77.185	GEMY COTE D'AZUR	REVISION
13/02/2024	57.259	CONTITRADE FRANCE	REMPLACEMENT PNEUS 4 SAISONS
29/01/2024	56.741	GEMY COTE D'AZUR	REVISION
	0		FILTRE A AIR RPLT
	0		REVISION
	0		DISQUES PLAQUETTES AV RPLT
	0		FILTRE CLIM RPLT
17/11/2023	44.558	NORAUTO SAS (PRODUIT SPE)	REMPLACEMENT PNEUS ETE
25/07/2023	25.572	GEMY COTE D'AZUR	REVISION