



MERCEDES-BENZ Vito: 0654-MPN

Vinnumber:	W1VVKBSZ7R4365605	Versionname:	Mercedes 114CDI 100kW furgón Pro larga furgón 100kW 4P manual
First Registrationdate:	5/04/2024	Fiscalpower:	
Expertise Mileage:	47900	Power Kw:	
Bodytype:	Transporter	Body colour	White
Gearbox:	Automatic	Type of rims (mounted)	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	2		
Number head rests	2		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Light Commercial Vehicle		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	1	Radio
Number keys remote	1	
Windows electric F		
Cruise Control		
Steering wheel multifunctional		
Type of climate control	Manual climate control	

Tyres

	225/55/17/107 H			
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/55 R 17 107 H
Tyre size FR				225/55 R 17 107 H
Tyre size RL				225/55 R 17 107 H
Tyre size RR				225/55 R 17 107 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Ignition key, Missing, Repair/replace (lump sum)



Door panel RR, Tear, Replace



Bumper F, Scratch(es), Paint



Bumper R, Scratch(es), Paint



Boot door panel RL, Dent(s), Repair and paint (complete)



Tyres, No damage, Check

