

2-ENX-180

2-ENX-180 · 1.5 HEV 2WD Dynamic · 28 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-ENX-180	Fuel Type	Hybrid Gasoline
Manufacturer	TOYOTA	VIN	JTDKBABB40A265327
Model	Yaris Cross	Cylinder Capacity	1.490 ^{cm³}
Model Versions	1.5 HEV 2WD Dynamic	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	05-12-2023
Color	Green	Odometer	89.071 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2023	Interior	Grey
KW	68	Number Headrests	5

Images





Accessories

ABS

Airbags

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Leather steering wheel

Rear view camera

Roller cover / parcel shelf

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance 16-06-2025

Last maintenance odometer 46.443

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	1 ^{mm}	Falken	205 ^{mm}	65 ^{mm}	16 ^{inch}	All Season
Rear Left	5 ^{mm}	Falken	205 ^{mm}	65 ^{mm}	16 ^{inch}	All Season
Front Right	1 ^{mm}	Falken	205 ^{mm}	65 ^{mm}	16 ^{inch}	All Season
Rear Right	5 ^{mm}	Falken	205 ^{mm}	65 ^{mm}	16 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part

Frontdoor – Right



Damage Type

Small dent(s)

Repair Type

Restyle

Acceptable

No



Damage Part

Wheelcover - Right Rear



Damage Type

Damaged

Repair Type

Replace

Acceptable

No



Damage Part

Reardoor – Right



Damage Type

Small scratch(es)

Repair Type

Touch-up / Polish

Acceptable

No



Damage Part

Overfender



Damage Type

Scratch(es)

Repair Type

Replace

Acceptable

No



Damage Part

Overfender



Damage Type

Dislocated / Loose

Repair Type

Repair

Acceptable

No



Damage Part

Wheelcover - Right Front



Damage Type

Damaged

Repair Type

Replace

Acceptable

No




Damage Part
Bumper – Front



Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Frontdoor – Left



Damage Type
Small dent(s)

Repair Type
Restyle


Acceptable
No



Damage Part
Tailgate



Damage Type
Small scratch(es)



Repair Type
Acceptable

Acceptable
Yes