



CITROËN C3: 2819-MFC

Vinnumber:	VF7SXYHTUNT665860	Versionname:	Citroen BlueHdi 75KW (100CV) S&S You! berlina con portón 75kW 5P manual
First Registrationdate:	24/02/2023	Fiscalpower:	
Expertise Mileage:	186847	Power Kw:	
Bodytype:	Berline	Body colour	White
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Steel		
Certificate of Conformity	No		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options

Number of keys total	1	Radio
Number keys remote	1	Luggage cover
Windows electric F		
Cruise Control		
Steering wheel multifunctional		
Type of climate control	Manual climate control	

Tyres

	185/65/15/92 T			
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				185/65 R 15 92 T
Tyre size FR				185/65 R 15 92 T
Tyre size RL				185/65 R 15 92 T
Tyre size RR				185/65 R 15 92 T
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	No
------------	-----------

MOT certificate, Missing, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Ignition key, Missing, Repair/replace (lump sum)



Air vent, mid-dashboard, Broken, Replace



Wheel bolt cover FL, Deformed / Strained, Replace



Door FL, Dent(s), Repair and paint (complete)



Wheel bolt cover RL, Missing, Replace



Bumper F, Broken, Replace and paint



Fog lamp L, Missing, Replace



Number plate F, Deformed / Strained, Repair/replace (lump sum)



Wheel bolt cover FR, Scratch(es), Replace



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Wing trim FR, Deformed / Strained, Replace



Sill trim R, Deformed / Strained, Replace



Wheel arch cover FR, Broken, Replace



Wheel bolt cover RR, Missing, Replace



Tyre repair kit, Missing, Repair/replace (lump sum)



Bumper R, Scratch(es), Repair and paint (complete)



Rear panel, Dent(s) and scratch(es), Repair and paint (complete)



Tyres, No damage, Check





Aerial, Missing, Replace



Roof, Dent(s), Repair and paint (complete)

