

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia											
				Policyholder				Opposite party				Opposite party company									
				Operation 2026		Claim number		Code / Agency				Date accident 03/07/2026									
				Expert code		Adjuster code		Policy number				Injured person can recover the VAT									
Date assignment 03/07/2026		Date first survey		Place GENOVA		C/O VAR		Repairs		Photo		Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)												Formerly plate									
Lessee / Co-owner												Date of overhaul									
Vehicle (Brand - Model - Version) RENAULT Captur 2ª serie Captur Full Hybrid E-Tech 145 CV Techno								Plate GZ817EZ		Vin Chassis VF1RJB00974621898				First Registration 08/04/2025							
Usage status NON CONOSCIUTO		Km 35330		Tyres % 50		Color NERO		Type of enamel METALLIZED				Consistency of damage		Type of Expert's report NOT DEFINITIVE							
Equipment																					
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0										Wheelbase		Seats No. 0		Axles 0	
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses															
Damaged items / restoration operations								SR		LA		VE		ME		D.M. S.C.		Costs of spare parts			
								Dif		Time		Dif		Time		Dif		Time			
1 Aggregate size of 2 elements								S				S				S					
1 620264889R Front bumper lower part								S				S				S					
1 62010P523R Front bumper upper part								S				S				S					
1 260107674R Headlight R								S				S				S					
1 266009347R Front light R								S				S				S					
1 638127184R Front wheel arch trim R								S				S				S					
1 620D66533R Front bumper side spoiler								S				S				S					
1 620840583R Lower trim of front bumper								S				S				S					
1 62010P713R Trim of front bumper								S				S				S					
1 765014093R Central pillar L								L				L				L					
1 Codice Ricambio Ossatura porta post. L								L				L				L					
1 963735760R External rear-view mirror cap L								L				L				L					
1 963747851R External rear-view mirror cap R								L				L				L					
1 631007255R Front mudguard R								L				L				L					
1 801018321R Front door L								L				L				L					
1 Codice Ricambio Parabrezza PRM																					
1 Codice Ricambio Igienizzante tessuto																					
1 Codice Ricambio Rettifica cerchio lega ant. L																					
1 Codice Ricambio Rettifica cerchio lega ant. R																					
1 Codice Ricambio Rettifica cerchio lega post. R																					
1 Codice Ricambio Cofano PRM																					
1 Codice Ricambio Tetto PRM																					
1 Codice Ricambio Porta ant. PRM R																					
1 Codice Ricambio Porta post. PRM R																					
1 Codice Ricambio Parafango post. PRM R																					
1 Codice Ricambio Paraurti post. PRM																					
1 Codice Ricambio Portellone post. PRM																					
1 Codice Ricambio Porta post. PRM L																					
1 Codice Ricambio Parafango post. PRM L																					
1 Codice Ricambio Parafango ant. PRM L																					
1 Codice Ricambio 2° chiave																					

New for old value (N)		Remarks PNEUM. 215/55R18, ANT. MICHELIN, POST. CONTINETAL. VHL SPORCO. SPIA MANUTENZIONE ATTIVA. KIT PNEUM. NON PRESENTE, VER. DOT. DI SERIE.	
-----------------------	--	--	--