MACADAM










Volkswagen Up: L533DS

Vinnumber:	**WVWZZZAAZMD024781**	Versionname:	**Up 1.0 48kW**
First Registrationdate:	**30/04/2021**	Fiscalpower:	
Expertise Mileage:	**50910**	Power Kw:	**48**
Bodytype:		Body colour	**Pure White Unilak**
Gearbox:	**MAN 5 VIT**	Paint type	**Opaque**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Petrol**	Parking lot	**462**
Number of seats	**4**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**
Manual climate control	
Radio multimedia	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	175 / 65 / 14 / 82 / T / Aluminium	4,9 mm	Continental	Winter
	Right	175 / 65 / 14 / 82 / T / Aluminium	5,1 mm	Continental	Winter
Rear	Left	175 / 65 / 14 / 82 / T / Aluminium	7,7 mm	Continental	Winter
	Right	175 / 65 / 14 / 82 / T / Aluminium	7,4 mm	Continental	Winter

Assistance equipment

Interior, Dirty, Chemical cleaning






Wing FL, Dent(s), Repair and paint (complete)





Outside rear-view mirror housing L, Scratch(es), Replace and paint




Bumper F, Scratch(es), Repair and paint (complete)





Wing RR, Dent(s) and scratch(es), Repair and paint (complete)




Door RR, Dent(s) and scratch(es), Repair and paint (complete)




Outer sill R, Dent(s), Repair and paint (complete)




Bumper R, Scratch(es), Repair and paint (complete)






Roof, Dent(s), Repair and paint (complete)





Onderhoudshistorie van: WVWZZZAAZMD024781

ALPHABET

Kenteken	L533DS
Merk Model	Volkswagen Up 1.0 48kW
Brandstofsoort	Benzine
Datum deel1	4/30/21

Datum reparatie	Kilometerstand	Reparatie omschrijving
11/4/25	36,561	Ruitenwisserblad(en) voorzijde
3/12/25	27,563	APK
3/12/25	27,563	Bougie
3/12/25	27,563	Luchtfilter
3/12/25	27,563	Onderhoudsbeurt
3/12/25	27,563	Remvloeistof
5/7/24	15,809	Ruitenwisserblad(en) voorzijde
1/25/24	12,870	Onderhoudsbeurt
11/18/22	7,842	Onderhoudsbeurt
11/18/22	7,842	Remvloeistof
11/18/22	7,842	Ruitenwisserblad(en) achterzijde
11/18/22	7,842	Ruitenwisserblad(en) voorzijde
7/6/21	0	Accu