




IDENTIFICATION VEHICLE

Driver name:	ASSE I
Make:	PEUGEOT
Model / version:	3008
Vin:	VF3M4DGZUNS029854
Plate:	2BQC755
Mileage:	75146
First registration:	11/02/2022
Color:	BLEU CLBES




ADDITIONAL INFORMATION


Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✗
Registration certificate:	✗
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book:	
Number of keys:	1
Original key:	✓

PICTURES





VIN INFORMATION

Radio
Système télématique
Projecteurs à allumage automatique
Lettre repère (J)
Largeur avant 7,5
Diamètre arrière 18
Indice de vitesse avant V
Largeur arrière 225
Finition intérieure Carbone
1.60 litre
Euro 6.3
Freins arrière à disques
Rétroviseurs rabattables électriques
Sièges avant à réglage lombaire
Aide au stationnement avant
Régulateur et limiteur de vitesse
Vitres portes arrière teintées foncées
détecteur de pluie essuie-vitre
Témoin d'oubli de ceinture arrière

Avertisseur d'angle mort
Facelift
déflecteur d'air plancher av

autodiagnostic OBD
déflecteur d'air double réglable pour radiateur
déflecteur d'air double réglable pour radiateur

rangée de boutons chromée
possibilité de réparation améliorée

câble de charge T2 pour connexion E/F

Radio avec système de navigation
Transmission automatique
Bandeaux de protection latérale chromés
Diamètre avant 18
Largeur arrière 7,5
Hauteur avant 55
Indice de vitesse arrière V
Climatisation automatique
Hybride essence
227 kw
Métallisée vernissée
Rétroviseur gauche à réglage mémorisé
Sièges avant réglable en hauteur
Direction assistée électrique variable
Aide au stationnement arrière
Lunette arrière teintée foncée
Vitres de portes arrière acoustiques
Airbag rideaux avant
Antiblocage de freinage ABS

palettes de sélection au volant
acoustique moyennement améliorée
gestion acoustique dynamique du bruit de la mécanique

fonctionnalité "Mirror Screen"
catalyseur inférieur à 50ppm

régulation ventilation automatique

pré-chauffage du carter
radiateur de 28 dm² et de 28 mm d'épaisseur en aluminium
kit réparation pneus

Prise USB
8 rapports
Matière : alliage
Diamètre arrière 18
Diamètre avant 18
Hauteur arrière 55
Largeur avant 225
Climatisation réfrigérant 1234YF
1598 cm3
308 ch
Freins avant à disques
Rétroviseur droit à réglage mémorisé
Siège avant gauche à réglage lombaire
Volant cuir
Caméra avec vision à 180°
Vitres de portes avant acoustiques
Vitres de custode teintées foncées
Airbag rideaux arrière
Freinage d'urgence assistée autonome (urbain)
depuis 01.22 16520
insonorisant tablier 7 kg
ventilateur électrique 200 W

fixation siège enfant
rétroviseur int jour/nuit automatique sans encadrement
pays froids

batterie 60 Ah EFR
Touchscreen HD 10"

rallonge traverse du train av

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	×	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	✓
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	1

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	3 mm			All-seasons		?
Front right	3 mm			All-seasons		?
Rear left	3 mm			All-seasons		?
Rear right	3 mm			All-seasons		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Certificate of registration (customer) 1	Missing
2	Certificate of conformity	Missing
3	Contact key	Missing
4	Compressor	Missing
5	Boot lid covering R	Dirty
6	Luggage compartment cover	Broken
7	Outside rear-view mirror housing L	
8	Door RL	Dent(s)
9	Wing RL	Scratch(es)
10	Tailgate / Boot	Scratch(es)
11	Door RR	Dent(s) and scratch(es)
12	Interior	Stain

Total: 12

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
---	----------	-------------	--------	----------	------------------

No damages present

DAMAGES DETAILS

1 - Certificate of registration (customer) 1 - Missing




2 - Certificate of conformity - Missing



3 - Contact key - Missing



4 - Compressor - Missing



5 - Boot lid covering R - Dirty



6 - Luggage compartment cover - Broken



7 - Outside rear-view mirror housing L



8 - Door RL - Dent(s)



9 - Wing RL - Scratch(es)



10 - Tailgate / Boot - Scratch(es)



11 - Door RR - Dent(s) and scratch(es)



12 - Interior - Stain



Expert

30/06/2026 13:45

A handwritten signature in black ink, consisting of a stylized 'S' followed by a horizontal line and a diagonal stroke.