MACADAM










Volkswagen Transporter: VLJ82H

Vinnumber:	**WV1ZZZ7HZMH113195**	Versionname:	**Transporter 6.1 2.0 TDI 110kW L1H1 GB 7-DSG**
First Registrationdate:	**24/08/2021**	Fiscalpower:	
Expertise Mileage:	**190652**	Power Kw:	**110**
Bodytype:		Body colour	**Paprika Red**
Gearbox:	**Automatic**	Paint type	**Opaque**
Transmission:		Type of rims (mounted)	**Steel**
Fueltype:	**Diesel**	Parking lot	**979**
Number of seats	**2**		
Type of rims (mounted)	**Steel**		
Maintenance needed	**No**		

Options

Number of keys total	**4**	Rear parking sensors	
GPS		Sliding door right-side	
Manual climate control			
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 65 / 16 / 107 / T / Steel	8,0 mm	Continental	All season
	Right	205 / 65 / 16 / 107 / T / Steel	8,3 mm	Continental	All season
Rear	Left	205 / 65 / 16 / 107 / T / Steel	7,1 mm	Continental	All season
	Right	205 / 65 / 16 / 107 / T / Steel	8,1 mm	Continental	All season

Assistance equipment

Ignition key, Broken, Replace



Interior, Dirty, Cleaning





Outside rear-view mirror housing L, Scratch(es), Replace




Door FL, Scratch(es), Repair and paint (complete)







Side wall RL, Dent(s), Repair and paint (complete)





Bonnet, Dent(s) and scratch(es), Repair and paint (complete)













Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)













Door FR, Dent(s) and scratch(es), Repair and paint (complete)









Outer sill R, Scratch(es), Repair and paint (complete)




Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)






Boot lid covering R, Broken, Replace




Bumper R, Scratch(es), Smart repair








Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)






Bodywork, Chemical polution, Polish








Onderhoudshistorie van: WV1ZZZ7HZMH113195

ALPHABET

Kenteken	VLJ82H
Merk Model	Volkswagen Transporter 6.1 2.0 TDI 110kW L1H1 GB 7-DSG
Brandstofsoort	Diesel
Datum deel1	8/24/21

Datum reparatie	Kilometerstand	Reparatie omschrijving
6/30/26	185,242	APK
6/30/26	185,242	Onderhoudsbeurt
6/30/26	185,242	Ruitenwisserblad(en) voorzijde
5/29/26	182,877	Vervanging band
2/9/26	174,239	Accu
8/13/25	157,106	Onderhoudsbeurt
8/13/25	157,106	Remvloeistof
8/13/25	157,106	Ruitenwisserblad(en) voorzijde
6/27/25	154,190	APK
6/27/25	154,190	Vervanging band
6/24/24	122,567	APK
6/24/24	122,567	Brandstoffilter
6/24/24	122,567	Luchtfilter
6/24/24	122,567	Onderhoudsbeurt
6/24/24	122,567	Remblokken achterzijde
6/24/24	122,567	Ruitenwisserblad(en) voorzijde
2/16/24	1	Remblokken voorzijde
2/16/24	1	Vervanging band
8/3/23	89,105	Onderhoudsbeurt
8/3/23	89,105	Remvloeistof
8/3/23	89,105	Reparatie band(en)
2/2/23	68,204	Vervanging band
12/23/22	62,591	Reparatie band(en)
12/6/22	60,386	Onderhoudsbeurt
6/27/22	43,193	Onderhoudsbeurt
3/22/22	30,991	Vervanging band
2/14/22	25,078	Onderhoudsbeurt