



PEUGEOT 3008: FT-389-EN

Vinnumber:	VF3M45GFRLS227273	Versionname:	PEUGEOT 3008 Puretech 180 S&S EAT8 GT LINE VP [5P] bva 8-180CH-10cv (SUV)
First Registrationdate:	5/10/2020	Fiscalpower:	
Expertise Mileage:	87772	Power Kw:	133
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Interior colour:	Black
Fueltype:	Petrol	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Steering wheel leather		Rear view camera	
Type of climate control	Autom climate control	Seat cover lining	Lining Other Lining Leather

Tyres

225/55/18/102 V				
Summer tyres:	Fr.L.	Continental: 5%	Fr.R.	Continental: 20%
	Re.L.	Michelin: 55%	Re.R.	Michelin: 65%
Tyre profile depth FL				7.8
Tyre profile depth FR				6.9
Tyre profile depth RL				4.6
Tyre profile depth RR				4.1
Tyre size FL				225/55 R 18 102 V
Tyre size FR				225/55 R 18 102 V
Tyre size RL				225/55 R 18 102 V
Tyre size RR				225/55 R 18 102 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)





Alloy rim RL bitone/polychrome, Scratch(es), Acceptable



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Bumper corner RR, Scratch(es), Paint



Historique Maintenance

Immatriculation: **FT-389-EN**Date de 1ère immatriculation: **05/10/2020**Modèle: **Peugeot 3008 Puretech 180 S&S EAT8 GT LINE VP [5P] bva 8-180CH-10cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
13/02/2026	86.424	STELLANTIS &YOU FRANCE SAS	AMORTISSEURS AR RPLT
	0		DISQUES PLAQUETTES AR RPLT
	0		BALAI ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		DIVERS CLIM
	0		FILTRE CLIM RPLT
	0		REVISION
	0		LIQUIDE DE FREIN
	0		RECYCLAGE
03/02/2025	72.067	STELLANTIS &YOU FRANCE SAS	ECLAIRAGE DE PLAQUE RPLT
	0		BATTERIE RPLT
	0		BOITIER D ALLUMAGE RPLT
	0		REVISION
	0		FILTRE A AIR RPLT
	0		FILTRE CLIM RPLT
	0		DIVERS CLIM
	0		BALAI ESSUIE GLACE AR
	0		BALAI ESSUIE GLACE AV
	0		DISQUES PLAQUETTES AV RPLT
18/10/2024	64.597	SARL CORON	CONTROLE TECHNIQUE
23/02/2024	46.803	STELLANTIS &YOU FRANCE SAS	JOINT DE COUVRE CULASSE RPLT
29/04/2024	44.887	STELLANTIS &YOU FRANCE SAS	PLAQUETTES AR RPLT
	0		REVISION
	0		BALAI ESSUIE GLACE AV AR
	0		PLAQUETTES AV RPLT
05/12/2022	22.117		LIQUIDE DE FREIN
	0		BALAI ESSUIE GLACE AV
	0		REVISION
	0		BALAI ESSUIE GLACE AR
	0		FILTRE CLIM RPLT
16/12/2021	11.656		REVISION
	0		BALAI ESSUIE GLACE AV

Historique Maintenance

Immatriculation: **FT-389-EN**

Date de 1ère immatriculation: **05/10/2020**

Modèle: **Peugeot 3008 Puretech 180 S&S EAT8 GT LINE VP [5P] bva 8-180CH-10cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
	0		BALAI ESSUIE GLACE AR