MACADAM









PEUGEOT 308: HA-580-GE

Vinnumber:	**VR3FPHPY1RY634639**	Versionname:	**PEUGEOT 308 Hybrid 136 e-DCS6 ALLURE VP [5P] bva 6-136CH-7cv (bi-corps)**
First Registrationdate:	**18/11/2024**	Fiscalpower:	
Expertise Mileage:	**128245**	Power Kw:	**100**
Bodytype:	**Berline**	Body colour	**Black**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Petrol**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**1**	Tow bar	
Number keys remote	**1**	Radio	
GPS big screen color		Central consol F	
GPS storage		Luggage cover	
GPS storage	**HD**	Headlights Xenon/LED/Laser	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Rear view camera	
Steering wheel multifunctional		Seat cover lining	**Lining Other** **Lining Leather**
Steering wheel leather			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**225/45/17/94 V**			
	Fr.L.	**Michelin: 85%**	Fr.R.	**Michelin: 90%**
	Re.L.	**Michelin: 60%**	Re.R.	**Michelin: 60%**

Tyre profile depth FL	**2.4**
Tyre profile depth FR	**2.0**
Tyre profile depth RL	**4.3**
Tyre profile depth RR	**4.2**
Tyre size FL	**225/45 R 17 94 V**
Tyre size FR	**225/45 R 17 94 V**
Tyre size RL	**225/45 R 17 94 V**
Tyre size RR	**225/45 R 17 94 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Inner door sill FL, Dent(s) and scratch(es), Repair and paint (complete)







Door panel RL, Scratch(es), Replace







Inner door sill RR, Chemical polution, Paint








Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Tyre FL, Out of tolerance, Replace





Tyre FR, Out of tolerance, Replace





Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)








Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)






Alloy rim FL bitone/polychrome, Scratch(es), Acceptable





Wing FL, Scratch(es), Acceptable





Outside rear-view mirror base L, Scratch(es), Acceptable




Door FL, Dent(s) and scratch(es), Repair and paint (complete)







Windscreen, Stone chip(s), Windscreen repair 3 stonechips





Bumper F, Scratch(es), Acceptable





Outer sill R, Scratch(es), Acceptable





Wing FR, Dent(s), Repair and paint (complete)





Bumper R, Deformed / Strained, Repair and paint (complete)







Boot lid covering R, Scratch(es), Replace







ALPHABET

Historique Maintenance

Immatriculation: **HA-580-GE** Date de 1ère immatriculation: **18/11/2024**

Modèle: **Peugeot 308 Hybrid 136 e-DCS6 ALLURE VP [5P] bva 6-136CH-7cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
18/08/2026	126.253	MARY AUTOMOBILES GRANVILLE	FORFAIT VIDANGE OCS
			LIQUIDE DE REFROIDISSEMENT RPLT
			FILTRE CLIM RPLT
			BALAI ESSUIE GLACE AR
			REVISION
			BALAIS ESSUIE GLACE AV
07/06/2026	107.996	PROFIL PLUS	PERMUTATIONS PNEUS
13/04/2026	100.520	MARY AUTOMOBILES GRANVILLE	FILTRE CLIM RPLT
			DISQUES PLAQUETTES AR RPLT
			REVISION
			BOITIER D ALLUMAGE RPLT
			REVISION ET CLIM
26/12/2025	74.538	MARY AUTOMOBILES GRANVILLE	REVISION ET CLIM
			FILTRE CLIM RPLT
			REVISION
			DISQUES PLAQUETTES AV RPLT
18/11/2025	67.732	PROFIL PLUS	PERMUTATIONS PNEUS
27/08/2025	50.065	MARY AUTOMOBILES GRANVILLE	REVISION
			BOITIER D ALLUMAGE RPLT
			BALAIS ESSUIE GLACE AV
			FILTRE A AIR RPLT
			FILTRE CLIM RPLT
			REVISION ET CLIM
			BALAI ESSUIE GLACE AR
24/04/2025	25.628	PROFIL PLUS	PERMUTATIONS PNEUS
11/04/2025	22.371	MARY AUTOMOBILES GRANVILLE	REVISION ET CLIM
			BALAI ESSUIE GLACE AR
			BALAIS ESSUIE GLACE AV
			REVISION
			FILTRE CLIM RPLT
10/01/2025	4.429	PROFIL PLUS	REMPLACEMENT PNEUS 4 SAISONS