

INSPECTION REPORT


End of contract

GENERAL INFO

File	312420
License plate	1YGK211
Vehicle identification number	W1K1771031J257837
Dossier	2019353177
Make	Mercedes A Berline 180 d
Mileage	57334
First registration	24/08/2020
client availability date	07/05/2026
inspectionDate	12/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
28	Front / Calendar / Replace	Y
44	Windshield / Trim / Replace	N
91	Rocker Panel Left // Smart Repair Medium	N
124	Light / Rear left / Replace	Y
125	Light / Rear Left On Rear Bonnet / Replace	Y
133	Bumper Rear // Painting	N
153	Rear Bonnet // Painting	N
165	Roof // Polish	Y
174	Light / Rear Right / Replace	Y
183	Wing Rear Right // Painting	N
196	Door Rear Right // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	N
210	Door Front Right // Smart Repair Small	N
233	Wing Front right // Painting	Y
316	Tyre Front Left // Replace	Y
346	Tyre Front Right // Replace	N
411	Seat Front Left // Repair	Y


Damage Pictures



Door Rear Right // Polish-scratch



Wing Rear Right // Painting-scratch



Rear Bonnet // Painting-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch




Light / Rear Right / Replace-scratch




Bumper Rear // Painting-scratch



Light / Rear left / Replace-scratch



Roof // Polish-scratch




Bumper Front // Painting-scratch



Windshield / Trim / Replace-scratch




Wing Front right // Painting-scratch




Seat Front Left // Repair-scratch




Door Front Right // Smart Repair Small-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Tyre Front Right // Replace-tear



Tyre Front Left // Replace-worn



Front / Calendar / Replace-bad position