



Renault Captur: R474GP

Vinnumber:	VF1RJ800969538618	Versionname:	Captur 1.6 E-Tech HEV 103kW RS-Line automaat
First Registrationdate:	30/08/2022	Fiscalpower:	
Expertise Mileage:	133033	Power Kw:	103
Bodytype:		Body colour	Two-tone Gris Cassiopée / Gris Highland
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Hybrid Petrol	Parking lot	438
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Lining semi-leather
GPS		Rear parking sensors
Autom climate control		Rear view camera
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 55 / 16 / 95 / H / Aluminium	5,0 mm	Continental	Summer
	Right	215 / 55 / 16 / 95 / H / Aluminium	6,1 mm	Continental	Summer
Rear	Left	215 / 55 / 16 / 95 / H / Aluminium	5,3 mm	Continental	Summer
	Right	215 / 55 / 16 / 95 / H / Aluminium	5,7 mm	Continental	Summer

Assistance equipment

Number of charging cables (rapid charge)	0
--	----------

Seat cover FL, Worn, Replace



Interior, Stain, Cleaning



Door FL, Scratch(es), Repair and paint (complete)



Door RL, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)



Door RR, Bad repair, Repair and paint (complete)



Door FR, Bad repair, Repair and paint (complete)



Wing RR, Bad repair, Repair and paint (complete)



Roof, Hail damage, Paintless dent repair (hail)



Kenteken	R474GP
Merk Model	Renault Captur 1.6 E-Tech HEV 103kW RS-Line automaat
Brandstofsoort	Benzine
Datum deel1	30-08-22

Datum reparatie	Kilometerstand	Reparatie omschrijving
09-04-26	119.994	APK
09-04-26	119.994	Onderhoudsbeurt
21-07-25	94.378	Bougie
21-07-25	94.378	Luchtfilter
21-07-25	94.378	Onderhoudsbeurt
21-07-25	94.378	Remvloeistof
23-05-25	89.432	Brandstof opvoerpomp
23-07-24	61.418	Bougie
23-07-24	61.418	Luchtfilter
23-07-24	61.418	Onderhoudsbeurt
14-08-23	33.706	Onderhoudsbeurt
14-08-23	33.706	Reparatie band(en)
03-03-23	18.279	Reparatie band(en)